



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 1201A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	NOT NECESSARY	983.20	-
1	FRONT SHOCK ABSORBER N/S	BENT	655.80	366.50
1	FRONT KNUCKLE ARM N/S	BENT	648.20	492.30
1	FRONT KNUCKLE ARM BEARING N/S	NECESSARY	599.80	220.00
1	FRONT LOWER ARM N/S	BENT	688.20	485.30
1	FRONT DRIVE SHAFT N/S	NOT NECESSARY	1,420.10	-
1	FRONT SPORT RIM N/S	WARPED / BENT	850.00	850.00
	LESS 20% DISCOUNT		-	-482.82
			5,845.30	1,931.28
<u>LABOUR</u>				
	TO CHECK WIRING.	NOT NECESSARY	50.00	-
	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE.		180.00	120.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	100.00
	TO DIAGNOSTIC & REPROGRAMME SYSTEM.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.		200.00	100.00
	TO PUTTY & SPRAY PAINTING.	NOT NECESSARY	250.00	-
			930.00	320.00
GRAND TOTAL			6,775.30	2,251.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,800.00

Report Ref No. CS/AGI22005856/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.