



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KHOR SAW THENG			Ref: CC4/ASM22005858/Apa3q2 Date: 16/06/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKW 3342S	Veh. Inspected	SMK 700B	
Policy No.	GA563782	Coverage (\$)	0.00	
Claim No.	S2M044MQ	Excess (\$)	0.00	
Assign From		Assign Date	20/06/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W. M3 CONVERTIBLE	c.c	3999	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WBSDX92090E437599	Colour	WHITE	
Odometer	78794 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	275/35 R19	MICHELIN	6 mm	
L/H Front Tyre	275/35 R19	MICHELIN	6 mm	
R/H Rear Tyre	275/35 R19	MICHELIN	6 mm	
L/H Rear Tyre	275/35 R19	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/06/2022	Inspection Date	20/06/2022	
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	