

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005861/VQY3E2**Date:** 20/02/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00156672100
Claimant Vehicle No :	SLL5834Y	Insured Vehicle No :	GBL6635S
Date of Loss:	16/06/2022	Nature of Claim:	TP
		Claim No:	SNM22D204286/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL5834Y	Engine No:	P520347156
Make & Model:	MAZDA 2, 1.5 (A)	Chassis No:	MM6DL2SAAGW196540
Reg. Date:	28/02/2017 (Man. Year: 2016)	Odometer:	107313 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,987.36	1,290.08	1,697.28	56.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	730.00	1,050.00	58.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,767.36	2,020.08	2,747.28	57.63
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	4,767.36	1,600.00	3,167.36	66.44

INSPECTION

Date of Assignment:	22/06/2022	
Date Inspected:	21/06/2022	Inspected At: SPEEDWERKZ PTE LTD (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre Singapore 147807
Estimated Period of Repair:	3.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2023)
Parts:	143	MAZDA 2 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL5834Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,125.00 FL	*867.00 FL
2	1		*RETAINER (LHS), FRONT BUMPER	Necessary	58.00 FL	*58.00 FL
3	1		*RETAINER (RHS), FRONT BUMPER	Necessary	58.00 FL	*58.00 FL
4	1		*BRACKET (LHS), FRONT BUMPER	Not Necessary	15.10 FL	*- FL
5	1		*BRACKET (RHS), FRONT BUMPER	Not Necessary	15.10 FL	*- FL
6	1		*LHS COVER, FRONT BUMPER	Not Necessary	28.00 FL	*- FL
7	1		*RHS COVER, FRONT BUMPER	Not Necessary	28.00 FL	*- FL
8	1		*COVER, TOWING	Not Necessary	68.00 FL	*- FL
9	1		*FRONT REINFORCEMENT	Not Necessary	444.50 FL	*- FL
10	1		*GRILLE TOP	Not Necessary	335.00 FL	*- FL
11	1		*RIVET, GRILLE TOP	Damaged	22.80 FL	*22.80 FL
12	1		*RIVET, GRILLE TOP	Damaged	34.80 FL	*34.80 FL
13	1		*BRACKET, GRILLE TOP	Not Necessary	102.40 FL	*- FL
14	1		*FASTENER, GRILLE TOP	Damaged	24.00 FL	*24.00 FL
15	1		*PLATE CENTER, GRILLE TOP	Not Necessary	33.40 FL	*- FL
16	1		*GRILLE	Cracked	119.60 FL	*119.60 FL
17	1		*CHROME (LHS), FRONT BUMPER	Cracked	176.70 FL	*176.70 FL
18	1		*CHROME (RHS), FRONT BUMPER	Cracked	176.70 FL	*176.70 FL
19	1		*BRACKET (LHS), GRILLE	Not Necessary	15.10 FL	*- FL
20	1		*BRACKET (RHS), GRILLE	Not Necessary	15.10 FL	*- FL
21	1		*FRONT PLATE, SET (REINFORCEMENT)	Not Necessary	92.70 FL	*- FL
22	1		*SUPPORT PANEL	Not Necessary	469.70 FL	*- FL
23	1		*UPPER SUPPORT PANEL	Not Necessary	124.00 FL	*- FL
24	1		*SET CLIP, FRONT BUMPER	Necessary	42.00 FS	*30.00 FS
25	1		*FRONT NUMBER PLATE	Cracked	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,703.70	1,597.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	716.34	307.52
Total Parts (\$\$)	2,987.36	1,290.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	80.00	30.00
2	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	800.00	400.00
3	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	300.00
4	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	0.00
Gross Labour Cost (\$\$)			1,780.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >