

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005863/UQY3M4**Date:** 19/07/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00068522101

Claimant Vehicle No : YQ1947B **Insured Vehicle No :** YM7920J

Date of Loss: 14/06/2022 Nature of Claim: TP Claim No: SNM22D204284/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YQ1947B**

Make & Model: ISUZU NMR85UH5A, 3.0 D (M) Engine No: 4JJ14E7446

Reg. Date: 17/02/2020 (Man. Year: 2019) Chassis No: JAANMR85HK7102507

Colour: White Odometer: 96992 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R16 Rear Tyre Size: 195/85 R16 (D/D)

Front Left Side: Citi 6 mm Rear Left Side: Citi 6/6 mm

Front Right Side: Citi 6 mm Rear Right Side: Citi 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,330.00	1,880.00	450.00	19.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,400.00	600.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,330.00	3,280.00	1,050.00	24.25
+ GST 7.00/7.00% (S\$)	303.10	229.60	73.50	24.25
Nett Amount (S\$)	4,633.10	3,509.60	1,123.50	24.25

INSPECTION

Date of Assignment: 20/06/2022

Date Inspected: 21/06/2022 Inspected At: 22 TAMPINES STREET 92
SINGAPORE 528876
REPAIRER: ETHOZ GROUP LTD

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Jul 2022)	
Parts:	N/A	ISUZU NMR85UH5A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ1947B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*INSULATION PANEL	Cracked	900.00 FS	*800.00 FS
2	1		*FIBER CORNER GUARD 14 FT RH	Broken	300.00 FS	*300.00 FS
3	2		*FIBER END CAP	Broken	150.00 FS	*150.00 FS
4	1		*FREEZER BOX BODY SEALANT	Necessary	180.00 FS	*180.00 FS
5	2		*ADVERTISEMENT STICKER	Necessary	800.00 FS	*450.00 FS
Total Parts (S\$)						2,330.00 1,880.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE FREEZER BOX REPAIR	New	1,400.00	1,100.00
2	TO SPRAY PAINT ON AFFECTED PORTIONS	New	600.00	300.00
Gross Labour Cost (S\$)			2,000.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >