

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3384G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	551.89	551.89
1	REAR UNDER COVER	NOT NECESSARY	654.96	-
1	REAR REINFORCEMENT	NOT NECESSARY	378.32	-
2	REAR BUMPER SIDE RETAINER RH / LH @\$112.70	N/S NECESSARY	225.40	112.70
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	55.00	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	LH TAIL UPPER LAMP	CRACKED	557.90	557.90
1	LH TAIL LOWER LAMP	CRACKED	570.00	570.00
1	LH FENDER	TO REPAIR SEE LABOUR	992.04	-
1	LH FENDER SHIELD	NOT NECESSARY	134.20	-
	LESS 25% DISCOUNT		-1,035.43	-453.62
			3,106.28	1,360.87
	NETT ITEMS			
1	PETROL STICKER (N)	NOT NECESSARY	20.00	-
1	REVERSE SENSOR (N)	NOT NECESSARY	135.70	-
	LESS 10% DISCOUNT		-15.57	-
			140.13	-
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF LH FENDER.		1,050.00	525.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE AND REAR UPHOLSTERY.		90.00	60.00
	CHECK LIGHTING.		60.00	30.00
	REMOVE AND REFIX REVERSE SENSOR.		60.00	40.00
			1,920.00	1,155.00
	GRAND TOTAL		5,166.41	2,515.87

Report Ref No. NS/INC22005864/Rnce2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,000.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC22005864/Rnce2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser