

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG122005867/VNY3E2

Date: 20/09/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SNG3373B **Insured Vehicle No :** XE6935C
Date of Loss: 18/06/2022 Nature of Claim: TP Claim No: CDMCG22001195

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNG3373B**
Make & Model: HYUNDAI I30 PDE, 1.4 T-GDI DCT (A) Engine No: G4LDJD232970
Reg. Date: 14/05/2019 (Man. Year: 2019) Chassis No: TMAH5H13VKJ015198
Colour: Brown Odometer: 47398 km
Engine Capacity: 1353 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,622.95	4,740.65	12,882.30	73.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,580.00	1,110.00	3,470.00	75.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,202.95	5,850.65	16,352.30	73.65
Approved Total (Overridden) (S\$)		4,650.00		
Nett Amount (S\$)	22,202.95	4,650.00	17,552.95	79.06

INSPECTION

Date of Assignment: 20/06/2022
Date Inspected: 22/06/2022 Inspected At: J.E.W Motor Pte Ltd (HQ)
60 Jalan Lam Huat #03-72 Carros Center
Singapore 737869
Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2022)
Parts:	144	HYUNDAI I30 PDE 1.4 T-GDI DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNG3373B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR OS DOOR	Repair	1,789.90 FL	*- FL
2	1		*REAR OS DOOR RUBBER	Serviceable	270.00 FL	*- FL
3	1		*REAR OS DOOR OUTER MOULDING	Serviceable	125.30 FL	*- FL
4	1		*REAR OS DOOR HANDLE	Serviceable	263.50 FL	*- FL
5	1		*REAR OS DOOR REGULATOR /GEAR	Serviceable	367.84 FL	*- FL
6	1		*REAR OS DOOR HINGE UPPER	Serviceable	173.88 FL	*- FL
7	1		*REAR OS DOOR HINGE LOWER	Serviceable	170.50 FL	*- FL
8	1		*REAR OS DOOR CHECK	Serviceable	85.92 FL	*- FL
9	1		*REAR OS DOOR TRIM BOARD	Serviceable	613.60 FL	*- FL
10	1		*ROCKER O/S PANEL OUTER GARNISH	Serviceable	715.60 FL	*- FL
11	1		*ROCKER OS PANEL OUTER	Serviceable	1,799.60 FL	*- FL
12	1		*ROCKER OS PANEL ENFORCEMENT	Serviceable	974.30 FL	*- FL
13	1		*REAR OS FENDER	Dented	1,768.30 FL	*1,768.30 FL
14	1		*REAR FENDER INNER PANEL	Serviceable	1,406.20 FL	*- FL
15	1		*REAR FENDER SHIELD FR PIECE	Cut	165.50 FL	*165.50 FL
16	1		*REAR FENDER AIR DUCT	Serviceable	87.30 FL	*- FL
17	1		*REAR FENDER TRIM BOARD	Serviceable	788.75 FL	*- FL
18	1		*REAR OS TYRE RIM	Scratched	899.36 FS	*750.00 FS
19	1		*REAR OS WHEELBEARING AND HUB ASSY	Bent	554.00 FL	*554.00 FL
20	1		*REAR OS TRAILING ARM	Serviceable	265.40 FL	*- FL
21	1		*REAR OS ASSIST ARM	Serviceable	227.90 FL	*- FL
22	1		*REAR OS SHOCK ABSORBER	Serviceable	230.50 FL	*- FL
23	1		*REAR OS SHOCK ABSORBER MOUNTING	Serviceable	133.10 FL	*- FL
24	1		*REAR OS ABSORBER STOPPER	Serviceable	137.60 FL	*- FL
25	1		*REAR OS ABSORBER COVER	Serviceable	175.60 FL	*- FL
26	1		*REAR CROSSMEMBER	Serviceable	1,468.70 FL	*- FL
27	1		*STABILIZER BAR	Serviceable	387.30 FL	*- FL
28	1		*STABILIZER LINK	Serviceable	147.30 FL	*- FL
29	1		*REAR OS UPPER ARM	Serviceable	239.50 FL	*- FL
30	1		*REAR OS LOWER ARM	Serviceable	393.10 FL	*- FL
31	1		*REAR OS KNUCKLE ARM	Bent	538.10 FL	*538.10 FL
32	1		*END PANEL	Serviceable	853.85 FL	*- FL
33	1		*REAR OS TAIL LAMP	Scratched	321.30 FL	*321.30 FL
34	1		*REAR OS REFLECTOR	Serviceable	295.10 FL	*- FL
35	1		*REAR BUMPER	Cut	811.11 FL	*811.11 FL
36	1		*REAR BUMPER SPONGE	Serviceable	79.20 FL	*- FL
37	1		*REAR BUMPER REINFORCEMENT	Serviceable	815.64 FL	*- FL
38	1		*REAR BUMPER REINFORCEMENT CENTRE	Serviceable	79.20 FL	*- FL
39	1		*REAR BUMPER OS SIDE BRACKET	Necessary	104.40 FL	*104.40 FL
40	1		*REAR BUMPER OS REFLECTOR	Cut	107.50 FL	*107.50 FL
41	1		*REAR BUMPER OS REFLECTOR GARNISH	Cut	85.60 FL	*85.60 FL
42	1		*REAR OS TYRE (70%)	Cut	280.00 FS	*196.00 FS
43	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
44	1		*REVERSE SENSOR	Cut	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$) **21,626.35** **5,631.81**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	500.00
2	SPRAY PAINTING CHARGE	New	1,500.00	400.00
3	WIRING CHARGE	New	150.00	30.00
4	TUFF COAT	New	100.00	30.00
5	TOWING CHARGE	New	150.00	50.00
6	REMOVE/REFIX UNDERCARRIAGE	New	150.00	70.00
7	RESET REAR ABS SYSTEM	New	200.00	0.00
8	TRANSFER OF DOOR MECHANISM REAR	New	150.00	0.00
9	RESET REAR POWER WINDOW SYSTEM	New	200.00	0.00
10	REMOVE & REFIT REVERSE SENSOR	New	180.00	30.00
Gross Labour Cost (\$\$)			4,580.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >