



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 9333U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SIDE MIRROR ROUND - LH	NOT NECESSARY	213.22	-
1	SIDE MIRROR SQUARE - LH TOP	NOT NECESSARY	128.68	-
1	SIDE MIRROR (S) - LH	BROKEN	213.22	213.22
1	SIDE MIRROR STAY - LH	TO REPAIR SEE LABOUR	980.51	-
1	SIDE MIRROR STAY BRACKET TOP - LH	NOT NECESSARY	155.47	-
1	SIDE MIRROR STAY BRACKET LOW - LH	NOT NECESSARY	156.19	-
	LESS 25% DISCOUNT		-461.82	-53.31
			1,385.47	159.91
	<u>LABOUR</u>			
	LABOUR TO REMOVE & REFIT SIDE MIRROR, SIDE MIRROR STAY, SIDE MIRROR BRACKET. INCLUSIVE OF THE REPAIR OF SIDE MIRROR STAY - LH.		480.00	100.00
			480.00	100.00
	GRAND TOTAL		1,865.47	259.91

RECOMMENDED COST OF REPAIRS			259.91
------------------------------------	--	--	---------------

Report Ref No. CS/FCI22005868/Ucy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.