

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS/FCI22005868/Ucy3e2	
	36 ROBINSON RO #16-01 CITY HOUS	AD SESINGAPORE 068877	Date:	16/08/2022	
			Code:	FCI2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SBS 6560L	Veh. Inspected	XE 9333U	
	Policy No.	D-19094111MFB	Coverage (\$)	0.00	
	Claim No.	D22001174MFBP	Excess (\$)	0.00	
	Assign From	AINI	Assign Date	20/06/2022	
2.	Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI FUSO FV51	c.c	11967	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	FV51SJA20125	Colour	BLUE	
	Odometer	378592 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	295/80 R22.5	GITI	6 mm	
	L/H Front Tyre	295/80 R22.5	GITI	6 mm	
	R/H Rear Tyre	295/80 R22.5 (D/D)	GITI	6/6/6/6 mm	
	L/H Rear Tyre	295/80 R22.5 (D/D)	GITI	6/6/6/6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT MIRROR.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/04/2022	Inspection Date	13/07/2022	
	Survey held at	MAH LIAN MOTOR VEHICLE RE	PAIRER		
		38 DEFU LANE 9 SINGAPORE 539278			
5a.	Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days				