# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/HLA22005870/UVY3E2

29/06/2022 Date:

**REFERENCE** 

Date of Loss:

Handling Insurer: HL Assurance Pte Ltd Policy No: MP318344

TP

**Claimant Vehicle** No:

SMJ7801C 18/06/2022 Insured Vehicle No: SLL6787T

> Claim No: MPC03504/LJ

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMJ7801C

Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A) Engine No: L15B5561204 Reg. Date: 20/03/2019 (Man. Year: 2018) Chassis No: RU11311182 Colour: Odometer: 29669 km Black

Nature of Claim:

**Engine Capacity:** 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Rear Left Side: Dunlop 7 mm Dunlop 7 mm Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,775.42	2,421.14	1,354.28	35.87
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,230.00	1,690.00	540.00	24.22
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,005.42	4,111.14	1,894.28	31.54
	Approved Total (Overridden) (S\$)		3,250.00		
	Nett Amount (S\$)	6,005.42	3,250.00	2,755.42	45.88

**INSPECTION** 

Date of Assignment: 21/06/2022

Date Inspected: 21/06/2022 Inspected At:

Progressive Automotive Pte Ltd (HQ) BLK 3022A UBI ROAD 1 #01-45/46,

Singapore 048716

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

# Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jun 2022)

Parts: M1-SUV HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMJ7801C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# **Recommended Parts**

No.	Qty	Part No. P	Particulars	Condition	Repairer's	Amount
1	1	*F	REAR BUMPER	Dented	553.10 FL	*553.10 FL
2	2	*F	REAR BUMPER SIDE HOLDER - LH / RH	Not Necessary	37.40 FL	*-FL
3	10	*F	REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
4	2	*F	REAR BUMPER REFLECTORS - LH / RH	Not Necessary	297.00 FL	*- FL
5	1	*F	REAR BOOT	Badly Dented	997.00 FL	*997.00 FL
6	1	*F	REAR BOOT GLASS MOULDING	Necessary	118.00 FL	*118.00 FL
7	1	*F	REAR BOOT VEZEL WORDINGS	Necessary	48.10 FL	*48.10 FL
8	1	*F	REAR BOOT RUBBER	Torn	95.02 FL	*95.02 FL
9	2	*F	REAR BOOT HINGES - LH / RH	Not Necessary	100.00 FL	*- FL
10	1	*F	REAR BOOT TOP LOCK	Bent	98.00 FL	*98.00 FL
11	1	*F	REAR BOOT BOTTOM LOCK	Not Necessary	27.00 FL	*- FL
12	1	*F	REAR BOOT INNER TRIM	Deformed / Twisted	167.40 FL	*167.40 FL
13	1	*F	REAR BOOT OUTER GARNISH WITH CHROME & EMBLEM	Not Necessary	235.10 FL	*- FL
14	2	*F	REAR BOOT LAMP - LH / RH	Not Necessary	720.00 FL	*- FL
15	1	*F	REAR END PANEL	Badly Dented	470.20 FL	*470.20 FL
16	1	*F	REAR END PANEL TOP GARNISH	Twisted	66.60 FL	*66.60 FL
17	2	*F	REAR NUMBER PLATE LAMP - LH / RH	Not Necessary	77.00 FL	*- FL
18	1	*L	LUGGAGE BOX	Not Necessary	168.10 FL	*- FL
19	1	*F	REAR NUMBER PLATE WITH CASING	Scratched	45.00 FS	*40.00 FS
20	2	*F	REAR SEALANT WINDSCREEN	Necessary	40.00 FS	*40.00 FS
21	1	*F	REAR SPONGE TAPE WINDSCREEN	Necessary	20.00 FS	*20.00 FS
22	1	*5	SET REAR BUMPER SENSOR	Shorted	220.00 FS	*200.00 FS
F=Fra	anchise	part. S=SpcNe	ett. L=ListItemDisc.	,		
				Cub Total (CC)	4 620 02	2 054 42

 Sub Total (\$\$)
 4,638.02
 2,951.42

 - List Item Discount on L Items 20.00/20.00% (\$\$)
 862.60
 530.28

**Total Parts (S\$)** 3,775.42 2,421.14

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO KNOCK OUT DENTS, CUT / WELD END PANEL, REMOVE, REPLACE ACCIDENT PARTS	New	800.00	700.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	800.00	600.00
3	TO CHECK WIRING	New	40.00	20.00
4	TO TRANSFER REAR BOOT GLASS	New	180.00	120.00
5	TO TUFF-KOTE	New	90.00	60.00
6	TO REMOVE AND REFIT END PANEL GARNISH, CARPET, CUSHION 8 RELATED PARTS TO FACILITATE REPAIRS	k New	120.00	80.00
7	TO REMOVE, REFIT / REPLACE REAR BUMPER SENSOR	New	120.00	50.00
8	TO TRANSFER REAR BOOT MECHANISM	New	80.00	60.00
	Gross Labou	r Cost (S\$)	2,230.00	1,690.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >