

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/GRB22001847/VQY3E2-1**Date:** 05/10/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : FBS4495E **Insured Vehicle No :** SLG3585E
 Date of Loss: 09/05/2021 Nature of Claim: TP Claim No: MFL2021D0002065

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBS4495E**
 Make & Model: YAMAHA XMAX, 250cc ABS Engine No: G3H4E0041337
 Reg. Date: 23/04/2021 (Man. Year: 2020) Chassis No: MH3SG3910LK034535
 Colour: Black Odometer: 0 km
 Engine Capacity: 250 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70-15 Rear Tyre Size: 140/70-14
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,704.00	5,301.00	12,403.00	70.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	480.00	1,350.00	73.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,534.00	5,781.00	13,753.00	70.41
Approved Total (Overridden) (S\$)		4,600.00		
Nett Amount (S\$)	19,534.00	4,600.00	14,934.00	76.45

INSPECTION

Date of Assignment: 20/06/2022
 Date Inspected: 28/02/2022 Inspected At: Tuck Life Pte Ltd (HQ)
 25 Kaki Bukit Road 4 Synergy #01-68
 Singapore 417800
 Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Oct 2022)	
Parts:	N/A	YAMAHA XMAX 250cc ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBS4495E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR ASSY	Punctured	1,034.00 F	*405.00 F
2	1		*RADIATOR HOSE	Not Necessary	55.00 F	*- F
3	1		*EXHAUST CAP	Serviceable	78.00 F	*- F
4	1		*EXHAUST SEAT	Not Necessary	55.00 F	*- F
5	1		*PROTECTOR MUFFLER 1	Grazed	134.00 F	*48.00 F
6	1		*PIPE EXHAUST 1	Repair	445.00 F	*- F
7	1		*REAR FAIRING RH	Cracked / Grazed	590.00 F	*300.00 F
8	1		*STAY FENDER RH	Serviceable	56.00 F	*- F
9	1		*STAY FENDER LH	Serviceable	56.00 F	*- F
10	1		*FRONT FENDER	Cracked	135.00 F	*135.00 F
11	1		*COVER SIDE RH	Cracked / Grazed	583.00 F	*150.00 F
12	1		*ASSIST GRIP RH	Serviceable	156.00 F	*- F
13	1		*COVER SIDE LH	Not Necessary	583.00 F	*- F
14	1		*ASSIST GRIP LH	Serviceable	156.00 F	*- F
15	1		*CROWN HANDLE	Dented	392.00 F	*337.00 F
16	2		*HOLDER HANDER UPPER	Serviceable	114.00 F	*- F
17	2		*HOLDER HANDLE LOWER	Serviceable	113.00 F	*- F
18	1		*FRONT FORK LH }	Bent	750.00 F	*798.00 F
19	1		*FRONT FORK RH }	Bent	750.00 F	*- F
20	1		*AXLE WHEEL	Bent	110.00 F	*45.00 F
21	1		*FRONT RIM	Serviceable	459.00 F	*- F
22	1		*FRONT BRAKE CALIPER ASSY	Not Necessary	231.00 F	*- F
23	1		*STEERING COVER UPPER 1	Not Necessary	351.00 F	*- F
24	1		*STEERING COVER UPPER 2	Not Necessary	325.00 F	*- F
25	1		*REAR VIEW MIRROR LH	Damaged	115.00 F	*115.00 F
26	1		*REAR VIEW MIRROR RH	Damaged	115.00 F	*115.00 F
27	1		*HANDLE BAR	Bent	352.00 F	*175.00 F
28	1		*GRIP ASSY LH	Torn	135.00 F	*42.00 F
29	1		*GRIP ASSY RH	Not Necessary	135.00 F	*- F
30	1		*END GRIP LH	Grazed	89.00 F	*60.00 F
31	1		*END GRIP RH	Not Necessary	89.00 F	*- F
32	1		*COVER HANDLE BAR LOWER 1	Serviceable	356.00 F	*- F
33	1		*THROTTLE CABLE ASSY	Not Necessary	119.00 F	*- F
34	1		*REAR FOOTREST ASSY LH	Not Necessary	435.00 F	*- F
35	1		*DUCT 1	Not Necessary	212.00 F	*- F
36	1		*COVER UNDER	Not Necessary	384.00 F	*- F
37	1		*STAND MAIN	Not Necessary	112.00 F	*- F
38	1		*STAND SIDE	Not Necessary	110.00 F	*- F
39	1		*FOOTREST COVER RH	Cracked	311.00 F	*145.00 F
40	1		*FOOTREST BOARD RH	Cracked	431.00 F	*180.00 F
41	1		*MAT RH	Cracked	79.00 F	*79.00 F
42	1		*FOOTREST COVER LH	Not Necessary	311.00 F	*- F
43	1		*FOOTREST BOARD LH	Not Necessary	431.00 F	*- F
44	1		*MAT LH	Not Necessary	79.00 F	*- F
45	1		*MOLE SIDE COVER LH	Not Necessary	321.00 F	*- F
46	1		*LEG SHIELD PANEL INNER PANEL RH	Cracked	211.00 F	*115.00 F

Report was unsubmitted during this print-out.

10/5/22, 11:20 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*LEG SHIELD	Cut	135.00 F	*135.00 F
48	1		*LEG SHIELD PANEL INNER LH	Not Necessary	211.00 F	*- F
49	1		*SCREEN	Cracked	102.00 F	*102.00 F
50	1		*STAY LEG SHIELD LH	Not Necessary	135.00 F	*- F
51	1		*STAY LEG SHIELD RH	Cut	135.00 F	*135.00 F
52	1		*COVER BATTERY	Not Necessary	110.00 F	*- F
53	1		*COVER FRONT	Cracked	430.00 F	*155.00 F
54	1		*WINDSCREEN COVER	Cracked	131.00 F	*131.00 F
55	1		*BODY COWLING LH	Not Necessary	422.00 F	*- F
56	1		*BODY COWLING RH	Cracked	422.00 F	*250.00 F
57	1		*GRILLE AIR INTAKE	Not Necessary	145.00 F	*- F
58	1		*SET FRONT FLASHER LIGHT ASSY	Cracked	139.00 F	*139.00 F
59	1		*METER ASSY	Not Necessary	890.00 F	*- F
60	1		*HEADLAMP ASSY	Cracked	1,129.00 F	*860.00 F
61	1		*GEAR SHIT SHAFT OIL SEAL	Not Necessary	24.00 FS	*- FS
62	1		*FORK OIL SEAL	Not Necessary	120.00 FS	*- FS
63	1		*FORK OIL	Not Necessary	60.00 FS	*- FS
64	1		*MOLE SIDE COVER RH	Cracked	321.00 F	*150.00 F
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	17,704.00 5,301.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING	New	380.00	100.00
2	TO REMOVE / REFIT, REPLACE FRONT FORK TUDES	New	350.00	80.00
3	SPRAY PAINTING	New	500.00	0.00
4	REPLACE, REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM	New	600.00	300.00
Gross Labour Cost (\$\$)			1,830.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >