



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 5404R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT CORNER PANEL RH	SERVICEABLE	483.22	-
1	FRT SIDE MIRROR RH	BROKEN	153.20	153.20
1	FRT SIDE MIRROR ARM RH	REFIT	187.90	-
1	FRT REFLECTOR LAMP RH	CRACKED / LOOP BROKEN	282.70	282.70
1	HEADLAMP RH	LOOP CRACKED	725.80	680.00
1	FRT SIDE LAMP RH	CRACKED	154.90	154.90
1	FRT BUMPER	DENTED / DISTORTED	827.20	827.20
1	FRT DOOR PANEL RH	TO REPAIR SEE LABOUR	1,463.70	-
	LESS 25% DISCOUNT		-1,069.66	-524.50
			3,208.96	1,573.50
<u>LABOUR</u>				
	TO REMOVE AND REINSTALL ELECTRICAL WIRING SYSTEM FOR NECESSARY REPAIRS. TO CHECK ELECTRICAL SYSTEM, REPAIR WIRE HARNESS AND FOCUS HEADLAMP.		50.00	30.00
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRT DOOR PANEL RH.		800.00	400.00
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		800.00	450.00
			1,650.00	880.00
GRAND TOTAL			4,858.96	2,453.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,950.00

Report Ref No. CS3/SMR22005877/Ety3e2-1

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.