

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005885/UPA3Q2**Date:** 07/11/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000010
Claimant Vehicle No :	SMW1564H	Insured Vehicle No :	GBH7358G
Date of Loss:	20/06/2022	Nature of Claim:	TP
		Claim No:	9707259831SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW1564H	Engine No:	G4FMLU173925
Make & Model:	HYUNDAI CN7 AVANTE, 1.6 DOHC CVT S (A)	Chassis No:	KMHLN41ETMU067779
Reg. Date:	04/11/2020 (Man. Year: 2020)	Odometer:	31851 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 7 mm	Rear Left Side:	Kumho 7 mm
Front Right Side:	Kumho 7 mm	Rear Right Side:	Kumho 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,844.20	4,330.48	12,513.72	74.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,740.00	1,980.00	3,760.00	65.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,584.20	6,310.48	16,273.72	72.06
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	22,584.20	5,000.00	17,584.20	77.86
+ GST 7.00/7.00% (S\$)	1,580.89	350.00	1,230.89	77.86
Nett Amount (S\$)	24,165.09	5,350.00	18,815.09	77.86
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,657.45		

INSPECTION

Date of Assignment:	21/06/2022		
Date Inspected:	21/06/2022	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	2,223.20 F	*2,023.20 FL
2	1		*BOOTLID REAR LOGO	Not Necessary	75.80 F	*- FL
3	1		*BOOTLID AVANTE EMBLEM	Necessary	42.00 F	*42.00 FL
4	1		*BOOTLID ELITE EMBLEM	Necessary	65.00 F	*65.00 FL
5	1		*BOOTLID REFLECTOR CENTRE	Not Necessary	1,162.20 F	*- FL
6	1		*BOOTLID INNER LOCK	Bent	148.00 F	*148.00 FL
7	1		*BOOTLID LOCK SWITCH	Not Necessary	101.40 F	*- FL
8	1		*BOOTLID WEATHERSTRIP	Twisted	166.00 F	*108.30 FL
9	1		*BOOTLID INNER TRIM	Not Necessary	265.00 F	*- FL
10	2		*BOOTLID HINGES	Not Necessary	290.00 F	*- FL
11	1		*BOOTLID OUTER TOP GARNISH	Not Necessary	1,125.80 F	*- FL
12	1		*BOOTLID OUTER TOP GARNISH INNER BRACKET	Not Necessary	250.00 F	*- FL
13	2		*BOOTLID OUTER TOP GARNISH INNER SIDE BRACKETS	Not Necessary	100.00 F	*- FL
14	1		*BOOTLID OUTER TOP SPOILER INNER (BLACK)	Not Necessary	450.00 F	*- FL
15	1		*SET BOOTLID REVERSE CAMERA	Not Necessary	745.00 F	*- FL
16	1		*REAR BUMPER	Dented / Deformed	481.00 F	*470.80 FL
17	1		*REAR BUMPER LOWER	Cracked	640.60 F	*640.60 FL
18	1		*REAR BUMPER CENTRE LAMP	Cracked	280.00 F	*201.50 FL
19	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 F	*- FL
20	2		*REAR BUMPER REFLECTORS	Not Necessary	116.40 F	*- FL
21	1		*REAR BUMPER SPONGE	Not fitted	245.00 F	*- FL
22	1		*REAR BUMPER REINFORCEMENT	Dented	329.00 F	*294.80 FL
23	2		*REAR BUMPER REINFORCEMENT BRACKETS	Not Necessary	302.00 F	*- FL
24	2		*REAR BUMPER REINFORCEMENT TOP BRACKETS	Twisted	50.00 F	*50.00 FL
25	3		*REAR BUMPER REINFORCEMENT LOWER BRACKETS	Twisted	75.00 F	*75.00 FL
26	4		*REAR BUMPER PDC SENSORS	Shorted	676.80 F	*676.80 FL
27	1		*SET REAR BUMPER PDC SENSOR WIRE	Not Necessary	236.10 F	*- FL
28	1		*REAR BUMPER UNDER COVER	Not Necessary	68.00 F	*- FL
29	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
30	1		*REAR END PANEL	Dented	537.00 F	*454.60 FL
31	1		*REAR END PANEL TOP GARNISH	Not Necessary	188.90 F	*- FL
32	2		*TAILLAMPS	Not Necessary	1,318.00 F	*- FL
33	2		*TAILLAMP HOUSING PANELS	Not Necessary	500.00 F	*- FL
34	1		*REAR EXHUAST	Not Necessary	981.00 F	*- FL
35	1		*REAR EXHUAST HEAT SHIELD	Not Necessary	145.00 F	*- FL
36	1		*REAR FLOOR PANEL	Not Necessary	1,215.00 F	*- FL
37	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	355.00 F	*- FL
38	1		*REAR WINDSCREEN MOULDING	Not Necessary	165.00 F	*- FL
39	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
40	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
41	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
42	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	300.00 FS	*- FS
43	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*REAR LICENCE PLATE	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,844.20	5,390.60
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,060.12
Total Parts (\$\$)	16,844.20	4,330.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY	New	120.00	80.00
5	TO RESET & DIAGNOSTIC BLIND SPOT SENSOR	New	500.00	0.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO DISMANTLE & REFIX FUEL TANK	New	80.00	0.00
8	TO CONDUCT CHASSIS ALIGNMENT	New	380.00	0.00
9	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
10	TO SPRAY RUST PROOFING	New	180.00	60.00
11	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,200.00	800.00
12	TO PUTTY & SPRAY PAINTING	New	1,800.00	900.00
			Gross Labour Cost (\$)	5,740.00
				1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >