

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22005887/UPA3Q2**Date:** 20/03/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MPC0002392_03
Claimant Vehicle No : SLP1231S **Insured Vehicle No :** SLU1939H
 Date of Loss: 21/06/2022 Nature of Claim: TP Claim No: MPC2022D0003247

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP1231S**
 Make & Model: FORD MONDEO, 2.0 HB TITANIUM (A) Engine No: GL54633
 Reg. Date: 26/05/2017 (Man. Year: 2016) Chassis No: WF0EXXWPCEGL54633
 Colour: Grey Odometer: 106372 km
 Engine Capacity: 1999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45Z R18 Rear Tyre Size: 235/45Z R18
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,967.30	15,758.40	28,208.90	64.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,350.00	3,750.00	2,600.00	40.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,317.30	19,508.40	30,808.90	61.23
Approved Total (Overridden) (S\$)		15,600.00		
Nett Amount (S\$)	50,317.30	15,600.00	34,717.30	69.00
+ Loss of Use (11.0 x S\$80.00/day) (S\$)		880.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		122.00		
Nett Liability (S\$)		16,604.00		
Global Sum Settlement (S\$)		16,600.00		

INSPECTION

Date of Assignment: 21/06/2022
 Date Inspected: 21/06/2022 Inspected At: Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2022)
Parts:	143	FORD MONDEO 2.0 HB TITANIUM (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP1231S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	2,966.20 F	*1,880.00 FL
2	1		*BOOTLID OUTER GARNISH	Dented / Deformed	1,680.00 F	*845.00 FL
3	1		*BOOTLID REAR LOGO	Necessary	120.00 F	*80.00 FL
4	1		*BOOTLID TITANIUM EMBLEM	Necessary	118.00 F	*75.00 FL
5	1		*BOOTLID MONDEO EMBLEM	Necessary	105.00 F	*70.00 FL
6	1		*BOOTLID ECO BOOST EMBLEM	Necessary	110.00 F	*70.00 FL
7	2		*BOOTLID REFLECTORS	Not Necessary	1,700.00 F	*- FL
8	1		*BOOTLID INNER LOCK	Twisted	680.00 F	*305.00 FL
9	1		*BOOTLID INNER TRIM	Deformed / Cracked	845.00 F	*490.00 FL
10	2		*BOOTLID HINGES	Not Necessary	300.00 F	*- FL
11	1		*BOOTLID WEATHERSTRIP	Twisted	315.00 F	*282.00 FL
12	1		*REAR BUMPER	Distorted	1,960.00 F	*1,650.00 FL
13	1		*REAR BUMPER BOTTOM	Distorted	1,450.00 F	*800.00 FL
14	2		*REAR BUMPER REFLECTORS	Not Necessary	210.00 F	*- FL
15	1		*REAR BUMPER SPONGE	Not fitted	188.00 F	*- FL
16	1		*REAR BUMPER BEAM	Bent	915.00 F	*620.00 FL
17	2		*REAR BUMPER BEAM BRACKETS	No such part	310.00 F	*- FL
18	1		*REAR BUMPER LOWER GARNISH	Cracked	299.00 F	*250.00 FL
19	2		*REAR BUMPER SIDE RETAINERS	Bent	330.00 F	*190.00 FL
20	1		*SET REAR BUMPER CLIPS	Necessary	45.00 F	*45.00 FL
21	2		*REAR BUMPER EXHAUST CHROMES	Serviceable	960.00 F	*- FL
22	4		*REAR BUMPER PDC SENSORS	Shorted (2 PCS ONLY)	720.00 F	*360.00 FL
23	2		*TAILLAMPS	Not Necessary	1,900.00 F	*- FL
24	2		*TAILLAMP HOUSING PANELS	Repair	510.00 F	*- FL
25	1		*REAR END PANEL	Dented	1,020.00 F	*790.00 FL
26	1		*REAR END PANEL TOP GARNISH	Twisted	399.00 F	*315.00 FL
27	1		*REAR FLOOR PANEL	Repair	1,280.00 F	*- FL
28	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	615.00 F	*- FL
29	1		*REAR EXHAUST	Not Necessary	688.10 F	*- FL
30	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	152.80 F	*- FL
31	1		*REAR FENDER	Not Necessary	1,907.00 F	*- FL
32	2		*REAR FENDER INNER TRIMS	Not Necessary	798.00 F	*- FL
33	1		*REAR WINDSCREEN MOULDING	Necessary	86.00 F	*86.00 FL
34	1		*BONNET	Repair	2,250.00 F	*- FL
35	1		*BONNET LOCK	Not Necessary	245.00 F	*- FL
36	1		*FRONT BUMPER	Dented / Deformed	1,950.00 F	*1,680.00 FL
37	2		*FRONT BUMPER SIDE RETAINERS	Necessary	290.00 F	*190.00 FL
38	1		*FRONT BUMPER LOWER CENTRE GRILLE	Cracked	850.00 F	*450.00 FL
39	1		*FRONT BUMPER SPONGE	Not fitted	244.10 F	*- FL
40	1		*FRONT BUMPER BEAM	Repair	950.00 F	*- FL
41	1		*FRONT BUMPER INNER BRACKET	Cracked	380.00 F	*305.00 FL
42	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
43	2		*FRONT PDC SENSORS	Shorted	360.00 F	*360.00 FL
44	2		*FRONT FOG LAMPS	Not Necessary	700.00 F	*- FL
45	1		*FRONT BUMPER LICENCE PLATE GARNISH	Deformed	105.00 F	*90.00 FL
46	1		*FRONT GRILLE	Cracked	920.00 F	*690.00 FL

Report was unsubmitted during this print-out.

3/20/23, 7:10 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT LOOG	Necessary	60.00 F	*60.00 FL
48	2		*HEADLAMPS	Cracked	5,600.00 F	*5,600.00 FL
49	1		*FRONT SUPPORT PANEL	Cracked	866.10 F	*820.00 FL
50	1		*AIR CON CONDENSER	Not Necessary	980.00 F	*- FL
51	1		*RADIATOR	Not Necessary	1,055.00 F	*- FL
52	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
53	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	200.00 FS	*- FS
54	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
55	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
56	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
57	1		*FRONT LICENCE PLATE	Bent	50.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					43,967.30	19,658.00
- List Item Discount on L Items 0.00/20.00% (\$\$)					0.00	3,899.60
Total Parts (\$\$)					43,967.30	15,758.40
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX REAR WINDSCREEN	New	120.00	120.00
7	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
8	TO REFILL AIR CON GAS	New	100.00	100.00
9	TO SPRAY RUST PROOFING	New	100.00	60.00
10	TO RESET & REPROGRAMME SYSTEM	New	180.00	50.00
11	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,800.00	1,400.00
12	TO PUTTY & SPRAY PAINTING	New	2,500.00	1,800.00
Gross Labour Cost (\$\$)			6,350.00	3,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >