


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *SLP12315*
 at Workshop m/s *Choom m/s*
 of _____
 Insured: *SLU1939H*
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: *\$74k.*
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: *10* days Res.: Yes or No
 Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

632D

Vehicle: IN / OUT

Date: _____ Person Contacted: *LTA 48394*

Veh No: *SLP12315* Yr Regn: *26/05/17*
 Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or *CA*
 Make: *Ford mondeo* c.c. *1999*
 Colour: *Grey* A/C: *Insured / Std / NI / NA*
 Sp.Reading: *106372* T/Radio: *Insured / Std / NI / NA*
 Eng/No: _____
 C/No: *WFOEXXWPC EAL 54633*
 Gen. Cond: *Good* / Fair / Poor / Burnt
 Steering: *In order* / Jammed / Leaked / Burnt or
 Brake: *In order* / Jammed / Leaked / Burnt or
 Modi: *Nil* / S/Rim / STD A/Rim or
 Tyre Size: F: *235/45-225*
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *Z Allen*

Front _____ Rear _____
 R/Bal. *6* mm R/Bal. *6* mm
 L/Bal. *6* mm L/Bal. *6* mm
 D.O.A. *21/06/22* D.O.I. *21/06/22*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Frt.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction *Dep 12k.*

Nett \$25606
have a/c
headly 3075

6/2/22 4/5 \$15,000 in bond Alan.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$ _____)

Transportation: _____

☐ : Interview (\$ _____)

Photos _____

☐ : Tech. Invs (\$ _____)

Others _____

☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Asher

Not Authorized
 Hike
 21/06/22
 2/5 @ 15,600
 10 days

CHOO MOTOR SPRAY PAINTER
 1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
 SINGAPORE 417883

VEHICLE No: SLP 1231S

1PC	BOOTLID	DO	1880	\$2,966.20	/
1PC	BOOTLID OUTER GARNISH	DO/OE	845	\$1,680.00	/
1PC	BOOTLID REAR LOGO	NEI	80	\$120.00	/
1PC	BOOTLID 'TITANIUM' EMBLEM	NEI	75	\$118.00	/
1PC	BOOTLID 'MONDEO' EMBLEM	NEI	70	\$105.00	/
1PC	BOOTLID 'ECO BOOST' EMBLEM	NEI	70	\$110.00	/
2PCS	BOOTLID REFLECTORS @\$850.00	NR		\$1,700.00	X
1PC	BOOTLID INNER LOCK	TRM	305	\$680.00	/
1PC	BOOTLID INNER TRIM	DE/CN	490	\$845.00	/
2PCS	BOOTLID HINGES @\$150.00	NR		\$300.00	X
1PC	BOOTLID WEATHRSTRIP	TRM	282	\$315.00	/
1PC	REAR BUMPER	DO.S	1650	\$1,960.00	/
1PC	REAR BUMPER BOTTOM	DO.S	800	\$1,450.00	/
2PCS	REAR BUMPER REFLECTORS @\$105.00	NR		\$210.00	X
1PC	REAR BUMPER SPONGE	NF		\$188.00	X
1PC	REAR BUMPER BEAM	Buf	620	\$915.00	/
2PCS	REAR BUMPER BEAM BRACKETS @\$105.00	NS		\$310.00	X
1PC	REAR BUMPER LOWER GARNISH	CN	250	\$299.00	/
2PCS	REAR BUMPER SIDE RETAINERS @\$165.00	Buf	95x2=190	\$330.00	/
1SET	REAR BUMPER CLIPS	NEI		\$45.00	/
2PCS	REAR BUMPER EXHAUST CHROMES @\$480.00	SC		\$960.00	X
4PCS	REAR BUMPER PDC SENSORS @\$180.00	SHIELD		\$720.00	2PCS 360
2PCS	TAILLAMPS @\$950	NR		\$1,900.00	X
2PCS	TAILLAMP HOUSING PANELS @\$255.00	R		\$510.00	X
1PC	REAR END PANEL	DO	790	\$1,020.00	/
1PC	REAR END PANEL TOP GARNISH	TRM	315	\$399.00	/
1PC	REAR FLOOR PANEL	R		\$1,280.00	X
1PC	REAR FLOOR PANEL TOP BOARD	SC		\$615.00	X
1PC	REAR EXHAUST	NR		\$688.10	X
1PC	REAR EXHAUST HEAT SHIELD	NR		\$152.80	X
1PC	REAR FENDER	NR		\$1,907.00	X
2PCS	REAR FENDER INNER TRIMS @\$399.00	NR		\$798.00	X
1PC	REAR WINDSCREEN MOULDING	NEI		\$86.00	/
1PC	BONNET	R		\$2,250.00	X
1PC	BONNET LOCK	NR		\$245.00	X
1PC	FRONT BUMPER	DO BE	1680	\$1,950.00	/
2PCS	FRONT BUMPER SIDE RETAINERS @\$145.00	NEI	95x2=190	\$290.00	/
1PC	FRONT BUMPER LOWER CENTRE GRILLE	CN	450	\$850.00	/
1PC	FRONT BUMPER SPONGE	NF		\$244.10	X
1PC	FRONT BUMPER BEAM	R		\$950.00	X
1PC	FRONT BUMPER INNER BRACKET	CN	305	\$380.00	/
1SET	FRONT BUMPER CLIPS	NEI		\$50.00	/
2PCS	FRONT PDC SENSORS @\$180.00	SHIELD		\$360.00	/

207

	FRONT FOG LAMPS @\$350.00	11	\$700.00	X
	FRONT BUMPER LICENCE PLATE GARNISH	22	\$105.00	✓
	FRONT GRILLE	CR2	\$920.00	✓
1PC	FRONT GRILLE LOGO	111	\$60.00	✓
2PCS	HEADLAMPS @\$2800.00	CR2	\$5,600.00	✓
1PC	FRONT SUPPORT PANEL	CR2	\$866.10	✓
1PC	AIR CON CONDENSER	11	\$980.00	X
1PC	RADIATOR	11	\$1,055.00	X
			\$43,537.30	

90
690

820
207

S.NETT				
1PC	REAR END PANEL SEALANT	111	\$50.00	✓
1SET	REAR FLOOR PANEL INSULATOR	11	\$200.00	X
1PC	REAR LICENCE PLATE W/HOLDER	11	\$50.00	X
1SET	BOOTLID INNER TRIM CLIPS	111	\$30.00	✓
1PC	REAR WINDSCREEN SEALANT	111	\$50.00	40
1PC	FRONT LICENCE PLATE	211	\$50.00	40

TO CHECK WIRING	\$50.00	30
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO TRANSFER BOOTLID MECHANISM	\$100.00	60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	X
TO DISMANTLE & REFIX REAR WINDSCREEN	\$120.00	✓
TO DISMANTLE & REFIX PETROL TANK	\$100.00	X
TO REFILL AIR CON GAS	\$100.00	✓
TO SPRAY RUST PROOFING	\$100.00	60
TO RESET & REPROGRAMME SYSTEM	\$180.00	50
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$2,800.00	1400
TO PUTTY & SPRAY PAINTING	\$2,500.00	1800
TOTAL	\$50,317.30	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

19498
202
115598.4
160
3750
19508.4
15606