



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 586T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT (N) (CONSISTENT)	BENT	984.00	984.00
1	REAR BOOTLID EMBLEM (OUTLANDER) (N) (CONSISTENT)	NECESSARY	55.00	55.00
1	REAR BUMPER (N) (CONSISTENT)	BENT	807.00	807.00
1	REAR BUMPER LOWER SPOILER (N) (CONSISTENT)	CRACKED	309.00	309.00
1	REAR BUMPER BRACKET (LEFT) (N) (CONSISTENT)	BENT	86.00	86.00
1	REAR WINDSCREEN MOULDING (N) (CONSISTENT)	NECESSARY	145.00	145.00
1	REAR LOWER SPOILER (END) (N) (CONSISTENT)	NO SUCH PARTS	220.00	-
	LESS 10% DISCOUNT		-	-238.60
			2,606.00	2,147.40
	<u>LABOUR</u>			
	LABOUR TO RENEW ABOVE PARTS.		600.00	400.00
	TO REINSTATE WINDSCREEN.		150.00	120.00
	TO RESPRAY ABOVE PARTS.		600.00	500.00
	TRANSFER TAILGATE ACCESSORIES.		80.00	60.00
			1,430.00	1,080.00
	GRAND TOTAL		4,036.00	3,227.40
	RECOMMENDED COST OF REPAIRS			3,227.40

Report Ref No. CS/ASM22005889/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.