



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNF 1369H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	MTG CRACKED	1,790.00	1,605.00
1	REAR BUMPER REINFORCEMENT	DISTORTED	85.00	85.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	798.00	-
1	REAR SLIDING DOOR RH	TO REPAIR SEE LABOUR	2,110.00	-
	LESS 25% DISCOUNT		-1,195.75	-422.50
			3,587.25	1,267.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
10	REAR BUMPER CLIPS @\$6.50 (SN)	NECESSARY	65.00	65.00
			65.00	65.00
	<b><u>LABOUR</u></b>			
	TO PANEL BEAT, REMOVE AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH AND REAR SLIDING DOOR RH.		600.00	500.00
	TO SPRAY PAINT AFFECTED AREA.		800.00	600.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	REMOVE & REFIX REVERSE SENSOR & DISTANCE SETTING.		80.00	50.00
			1,730.00	1,150.00
	<b>GRAND TOTAL</b>		<b>5,382.25</b>	<b>2,482.50</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,950.00</b>

Report Ref No. CS/SMO22005893/Kvy3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.