

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|---|---|-----------------|-------|-----------------------|--|
| | SOMPO INSURAN | ICE SINGAPORE PL | | Ref: | CS/SMO22005893/Kvy3e2 | |
| | 50 RAFFLES PLAC SINGAPORE LAN | CE #03-03 D TOWERSINGAPORE 048623 | | Date: | 26/08/2022 | |
| | | | | Code: | SMO | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SKP 2872Y | Veh. Inspected | k | SNF 1369H | |
| | Policy No. | D21MTPV01014840 | Coverage (\$) | | 0.00 | |
| | Claim No. | CMTD2201804/MYE | Excess (\$) | | 0.00 | |
| | Assign From | GRACE TEO | Assign Date | | 21/06/2022 | |
| 2. | 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | TOYOTA ALPHARD (A) | c.c | | 2493 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2022 | |
| | Chassis No. | AYH300141230 | Colour | | METALLIC BLACK | |
| | Odometer | 13608 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | STANDARD ALLOY RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 225/60 R17 | YOKOHAMA | | 6 mm | |
| | L/H Front Tyre | 225/60 R17 | YOKOHAMA | | 6 mm | |
| | R/H Rear Tyre | 225/60 R17 | YOKOHAMA | | 4 mm | |
| | L/H Rear Tyre | 225/60 R17 | YOKOHAMA | | 4 mm | |
| 4. | 4. Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 24/05/2022 | Inspection Date | te | 21/06/2022 | |
| | Survey held at | MY CAR CONSULTANT PTE LT | D | | | |
| | | 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869 | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | | |
| | | | | | | |