

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22005894/UQY3E2

Date: 05/07/2022

REFERENCE

Insured/Claimant: CHIA ENG BENG Policy No: DMPCSNW00252742100

Date of Loss: 17/06/2022 Nature of Claim: OD Claim No: SNM22D204265/C01/CHEESC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX4926X**
Make & Model: PEUGEOT 3008, 1.6 D e-HDi ETG Active (A) Engine No: 10JBFT0099763
Reg. Date: 16/12/2015 (Man. Year: 2015) Chassis No: VF30U9HD8FS231177
Colour: Brown Odometer: 86220 km
Engine Capacity: 1560 cc
Market Value/New Car Price: S\$46,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,825.00	4,375.00	1,450.00	24.89
Miscellaneous Items	50.00	25.00	25.00	50.00
Labour	600.68	571.28	29.40	4.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,475.68	4,971.28	1,504.40	23.23
Approved Total (Overridden) (S\$)		3,950.00		
(S\$)	6,475.68	3,950.00	2,525.68	39.00
+ GST 7.00/7.00% (S\$)	453.30	276.50	176.80	39.00
Nett Amount (S\$)	6,928.98	4,226.50	2,702.48	39.00

INSPECTION

Date of Assignment: 21/06/2022 Present Location: Car City Auto Centre Pte Ltd (HQ)
Date Inspected: 27/06/2022 Inspected At: Car City Auto Centre Pte Ltd (HQ)
Estimated Period of Repair: 4.0 days Blk 9006 #01-198, Tampines Street 93
Singapore 528840

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2022)
Parts:	M1-SUV	PEUGEOT 3008 1.6 D e-HDi ETG Active (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX4926X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		5,825.00 F	*4,375.00 F
Total Parts (\$\$)						4,375.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRA	50.00	25.00
Sub Total (\$\$)			50.00	25.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	231.00	201.60
2	SPRAY PAINT	New	369.68	369.68
Gross Labour Cost (\$\$)			600.68	571.28

Report was unsubmitted during this print-out.

< END OF ESTIMATES >