

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA22005895/EQY3E2

Date: 15/07/2022

REFERENCE

Insured/Claimant:	SAN KO KO WIN	Policy No:	MP319092		
Date of Loss:	20/06/2022	Nature of Claim:	OD	Claim No:	MPC03503/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW1937R	Engine No:	3ZRB744856
Make & Model:	TOYOTA HARRIER, 2.0 Elegance (A)	Chassis No:	ZSU600074403
Reg. Date:	10/11/2016 (Man. Year: 2016)	Odometer:	54853 km
Colour:	White		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,068.50	1,963.50	105.00	5.08
Miscellaneous Items	115.00	85.00	30.00	26.09
Labour	2,360.00	1,840.00	520.00	22.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,543.50	3,888.50	655.00	14.42
Approved Total (Overridden) (\$\$)		3,100.00		
- Excess (\$\$)	0.00	775.00	-775.00	
(\$\$)	4,543.50	2,325.00	2,218.50	48.83
+ GST 7.00/7.00% (\$\$)	318.05	162.75	155.30	48.83
Nett Amount (\$\$)	4,861.55	2,487.75	2,373.80	48.83

INSPECTION

Date of Assignment:	20/06/2022	Present Location:	Wah Hong Motors & Credit Pte Ltd (HQ)
Date Inspected:	21/06/2022	Inspected At:	Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581
Estimated Period of Repair:	7.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jul 2022)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW1937R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bumper (WCP)	Broken	280.00 F	*280.00 F
2	1		*Front bumper side retainer LH/RH @2*\$50 (WCP)	Not Necessary	100.00 F	*- F
3	1		*Center grille assy (WCP)	Cut	200.00 F	*200.00 F
4	1		*Rear door RH (WCP)	Dented	580.00 F	*580.00 F
5	1		*Rear fender RH (WCP)	Dented	580.00 F	*580.00 F
6	1		*Rear windscreen moulding (WCP)	Necessary	60.00 F	*60.00 F
7	1		*Front bumper lower skirt (WCP)	Cut	170.00 F	*170.00 F
8	1		*Rear bumper (Repair refer to labor) (NPA)	Repair	0.00 F	*- F
9	1		*Support panel (Repair refer to labor) (NPA)	Not Necessary	0.00 F	*- F
						F=Franchise part.
					Sub Total (\$\$)	1,970.00 1,870.00
					+ Margin on L,N Items 5.00/5.00% (\$\$)	98.50 93.50
					Total Parts (\$\$)	2,068.50 1,963.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	center grille clips (NECESSARY)	30.00	15.00
2	1	Front bumper clips (NECESSARY)	35.00	30.00
3	1	Rear fender sealant (NECESSARY)	50.00	40.00
Sub Total (\$\$)			115.00	85.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	1,000.00	900.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	1,000.00	800.00
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	60.00	30.00
4	To remove and refit/replace Front door RH fitting, trimmings, garnish, window glass and lock mechanism	New	100.00	30.00
5	To remove and refit rear seat in order to repair	New	100.00	30.00
6	To remove and refit/replace roots lining & upholster garnish	New	100.00	50.00
Gross Labour Cost (\$\$)			2,360.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >