

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 22.29612 Date: 26<sup>th</sup> July 2022

Our Ref: CS3/ASM21012691/Bqy3e2-1

## M/s Axa Insurance Pte Ltd

C/o Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBK 385H

INSURED VEHICLE: XD 2680T ACCIDENT DATE: 13/12/2021

We thank you for your instruction on 13/06/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBK 385H from M/s KTO Automobile Assessors.
- b) Singapore Accident Statement of Vehicles GBK 385H and XD 2680T
- c) Final Repair Bill of GBK 385H from M/s Wah Yu Automotive Body Work.
- d) Colour damaged vehicle photographs of GBK 385H.

Pre-Repair Inspection Date: 15/12/2021 at M/s Wah Yu Automotive Body Work, 176 Sin Ming Drive #05-09, Singapore 575721.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : GBK 385H

Make & Model : Toyota Dyna 150 5MT

Year of Registration : 2019

Chassis Number : JTFAT35Y30K214455

Engine Capacity : 2982 cc

- 2. We recommend that the repairs of the entire damage require about <u>6 (Six)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.