

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005896/VQY3Q2**Date:** 28/11/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00027112201

Claimant Vehicle No : SKP570G**Insured Vehicle No :** SMU486S

Date of Loss: 17/06/2022

Nature of Claim: TP

Claim No: SNM22D204263/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKP570G**

Make & Model: TOYOTA 86, 2.0 (A)

Engine No: FA20H837558

Reg. Date: 11/08/2014 (Man. Year: 2013)

Chassis No: JF1ZN6K72EG018578

Colour: Blue

Odometer: 91141 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size:

225/40 R18

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 7 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,040.45	11,350.13	3,690.32	24.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,500.00	2,390.00	4,110.00	63.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,540.45	13,740.13	7,800.32	36.21
Approved Total (Overridden) (S\$)		11,000.00		
(S\$)	21,540.45	11,000.00	10,540.45	48.93
+ GST 7.00/7.00% (S\$)	1,507.83	770.00	737.83	48.93
Nett Amount (S\$)	23,048.28	11,770.00	11,278.28	48.93

INSPECTION

Date of Assignment: 21/06/2022

Date Inspected: 21/06/2022 Inspected At:

Teamwork Garage Pte Ltd (HQ)

53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
Singapore 408934

Estimated Period of Repair: 7.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2022)
Parts:	M1-COUPE	TOYOTA 86 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP570G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	1,193.06 FL	*1,193.06 FL
2	2		*REAR BUMPER BRACKET	No	95.24 FL	*60.00 FL
3	1		*REAR BUMPER RETAINER (2 PCS)	Necessary	54.97 FL	*54.97 FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	583.44 FL	*530.40 FL
5	1		*REAR BUMPER SIDE COVER (2 PCS)	Necessary	84.41 FL	*84.41 FL
6	2		*REAR BUMPER TOW COVER	Necessary	41.86 FL	*41.86 FL
7	1		*REAR BUMPER BRAKE LIGHT	Cracked	568.81 FL	*568.81 FL
8	1		*BOOTLID	Dented	1,473.89 FL	*1,339.90 FL
9	1		*BOOTLID EMBLEM -LOGO	Necessary	165.44 FL	*165.44 FL
10	1		*BOOTLID OUTER GARNISH	Necessary	298.32 FL	*298.32 FL
11	2		*BOOTLID HINGE	Cut	606.32 FL	*551.20 FL
12	1		*BOOTLID LOCK	Jammed	345.00 FL	*345.00 FL
13	1		*BOOTLID LOCK STRIKER	Bent	81.73 FL	*81.73 FL
14	1		*BOOTLID WEATHERSTRIP	Deformed	168.50 FL	*168.50 FL
15	1		*BOOTLID INNER TRIM	Cut	166.54 FL	*166.54 FL
16	1		*BOOTLID SPOILER	Dented	2,975.28 FL	*2,704.80 FL
17	1		*END PANEL	Dented	588.28 FL	*588.28 FL
18	1		*END PANEL TOP GARNISH	Cut	134.31 FL	*134.31 FL
19	2		*REAR FENDER INNER TRIM BOARD	Cut	444.80 FL	*444.80 FL
20	2		*REAR FENDER AIRVENT	Serviceable	163.49 FL	*- FL
21	1		*REAR FENDER INNER SHIELD	O/S Cut	329.56 FL	*164.78 FL
22	1		*SPARE TYRE COMPARTMENT TOP BOARD	Bent	659.89 FL	*659.89 FL
23	1		*SPARE TYRE COMPARTMENT	Dented	788.81 FL	*788.81 FL
24	1		*SPARE TYRE COMPARTMENT SPONGE	No such part	284.46 FL	*- FL
25	1		*EXHAUST SILENCER	Dented	1,895.96 FL	*1,723.60 FL
26	2		*EXHAUST SILENCER MOUNTING	Dented	59.62 FL	*59.62 FL
27	1		*EXHAUST SILENCER HEATSHIELD	Serviceable	152.13 FL	*- FL
28	1		*MIDPIPE	Not Necessary	1,370.05 FL	*- FL
29	1		*TAILLAMP	O/S Cracked	1,903.88 FL	*951.00 FL
30	1		*REAR SENSOR WIRING	Not Necessary	195.25 FL	*- FL
31	1		*KEYLESS SENSOR	Broken	207.46 FL	*207.46 FL
32	1		*KEYLESS SPEAKER	Serviceable	141.90 FL	*- FL
33	1		*REAR SEAT UNDER PANEL	Repair	339.13 FL	*- FL
34	1		*REAR NUMBER PLATE LAMP	Serviceable	76.12 FL	*- FL
35	1		*SET REVERSE SENSOR	Cut	250.00 FS	*200.00 FS
36	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
37	1		*SET FENDER INNER TRIM BOARD CLIP	Necessary	50.00 FS	*30.00 FS
38	1		*SET END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*30.00 FS
39	1		*SET TAILGATE INNER TRIM BOARD CLIP	Necessary	50.00 FS	*30.00 FS
40	1		*REAR NUMBER PLATE	Dented	80.00 FS	*40.00 FS
41	1		*JOINT SEALANT	Necessary	120.00 FS	*60.00 FS
42	1		*WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
43	1		*SPARE TYRE COMPARTMENT SPONGE LH	Torn	208.01 FL	*208.01 FL
44	1		*SPARE TYRE COMPARTMENT SPONGE RH	Torn	208.01 FL	*208.01 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

11/28/22, 11:43 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (\$)	19,803.93	14,973.51
				- List Item Discount on L Items 25.00/25.00% (\$)	4,763.48	3,623.38
				Total Parts (\$)	15,040.45	11,350.13
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTING SYSTEM	New	150.00	30.00
2	REMOVE TRIMS & GARNISHES TO FACILITATE REPAIR	New	200.00	70.00
3	REMOVE & REPLACE REVERSE SENSOR	New	150.00	40.00
4	REMOVE & REPLACE EXHAUST SILENCER	New	200.00	70.00
5	REMOVE & REPLACE MIDPIPE	New	200.00	30.00
6	REMOVE & REPLACE BOOTLID ATTACHMENT	New	150.00	50.00
7	MOUNT VEHICLE ON BENCH FOR CHASSIS REPAIR	New	500.00	100.00
8	REMOVE & REFIT FUEL TANK TO FACILITATE REPAIR	New	200.00	70.00
9	REMOVE AND REFIT REAR SEAT TO FACILITATE REPAIR	New	200.00	0.00
10	PANEL BEATING ON AFFECTED AREAS	New	2,200.00	1,000.00
11	SPRAY PAINTING ON AFFECTED AREAS	New	2,200.00	900.00
12	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (\$)			6,500.00	2,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >