

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS22005897/ANY3M4**Date:** 04/04/2023**REFERENCE**

Insured/Claimant:	CHONG KHIN LUNG	Policy No:	SP2000692339
Date of Loss:	07/06/2022	Nature of Claim:	OD
		Claim No:	202222005265JK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL8302H		
Make & Model:	OPEL INSIGNIA GRANDSPORT AWD B20NFT, 2.0 (A)	Engine No:	T2172228HARX0754
Reg. Date:	11/12/2020 (Man. Year: 2017)	Chassis No:	W0VZT6EC0J1068966
Colour:	Grey	Odometer:	5047 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35R20	Rear Tyre Size:	245/35R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,242.95	24,493.25	9,749.70	28.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,740.00	7,055.00	6,685.00	48.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	47,982.95	31,548.25	16,434.70	34.25
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	47,282.95	30,848.25	16,434.70	34.76
+ GST 8.00/8.00% (S\$)	3,782.64	2,467.86	1,314.78	34.76
Nett Amount (S\$)	51,065.59	33,316.11	17,749.48	34.76

INSPECTION

Date of Assignment: 20/06/2022

Date Inspected: 22/06/2022

Inspected At:

AUTO GERMANY PTE LTD
7 UBI CLOSE, ALPINE CENTRE
SINGAPORE 408604

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2023)
Parts:	143	OPEL INSIGNIA GRANDSPORT AWD B20NFT 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL8302H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Dented	2,557.00 FL	*2,557.00 FL
2	1		*FRT BONNET LOCK	Not Necessary	170.00 FL	*- FL
3	1		*FRT BONNET LOCK BRACKET	Bent	280.00 FL	*280.00 FL
4	5		*FRT BONNET INSULATOR CLIP	Not Necessary	32.50 FL	*- FL
5	1		*FRT BUMPER	Deformed	1,764.00 FL	*1,764.00 FL
6	1		*FRT BUMPER TOW COVER	Not Necessary	139.00 FL	*- FL
7	1		*FRT BUMPER NUMBER PLATE BASE	Not Necessary	232.00 FL	*- FL
8	10		*FRT BUMPER CLIP	Necessary	65.00 FL	*32.50 FL
9	1		*FRT BUMPER SIDE RETAINER LH - GUIDE	Not Necessary	151.00 FL	*- FL
10	1		*FRT BUMPER SIDE RETAINER RH - GUIDE	Not Necessary	151.00 FL	*- FL
11	1		*FRT BUMPER BRACKET LH	Cracked	172.00 FL	*172.00 FL
12	1		*FRT BUMPER BRACKET SUPPORT LH	Cracked	136.00 FL	*136.00 FL
13	1		*FRT BUMPER BRACKET RH	Cracked	172.00 FL	*172.00 FL
14	1		*FRT BUMPER BRACKET SUPPORT RH	Cracked	136.00 FL	*136.00 FL
15	1		*FRT BUMPER BRACKET TOP CENTRE	Bent	284.00 FL	*284.00 FL
16	1		*FRT BUMPER PEDESTRIAN IMPACT SRS SENSOR	Damaged	513.00 FL	*513.00 FL
17	1		*FRT BUMPER SPONGE	Cracked	238.00 FL	*238.00 FL
18	1		*FRT BUMPER SPONGE SUPPORT	Cracked	238.00 FL	*238.00 FL
19	1		*FRT BUMPER REINFORCEMENT UPP - CRASH LIMITER	Dented	799.00 FL	*799.00 FL
20	2		*FRT BUMPER PARKING SENSOR	Not Necessary	788.00 FL	*- FL
21	1		*FRT BUMPER BLIND SPOT SENSOR	Not Necessary	391.00 FL	*- FL
22	6		*FRT BUMPER PARKING SENSOR SEAL	Necessary	102.00 FL	*102.00 FL
23	1		*FRT BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	331.00 FL	*- FL
24	1		*FRT GRILLE ASSY	Cracked	1,590.00 FL	*1,590.00 FL
25	1		*FRT GRILLE LOGO	Necessary	204.00 FL	*204.00 FL
26	1		*RH HEADLAMP	Not Necessary	5,404.00 FL	*- FL
27	1		*LH HEADLAMP	Cracked	5,404.00 FL	*5,404.00 FL
28	1		*RADIATOR SUPPORT PANEL TOP GARNISH	Deformed	166.00 FL	*166.00 FL
29	1		*A/C WARNING LABEL	Necessary	27.00 FL	*27.00 FL
30	1		*RADIATOR SUPPORT PANEL TOP	Repair	498.00 FL	*- FL
31	1		*A/C CONDENSER	Not Necessary	1,658.00 FL	*- FL
32	1		*A/C CONDENSER SUPPORT - BRACKET	Not Necessary	237.00 FL	*- FL
33	1		*A/C CONDENSER AIR GUIDE LOW CENTRE	Not Necessary	166.00 FL	*- FL
34	1		*A/C CONDENSER AIR GUIDE RH	Not Necessary	148.00 FL	*- FL
35	1		*A/C CONDENSER AIR GUIDE LH	Cracked	150.00 FL	*150.00 FL
36	1		*ENGINE AIR INTAKE RESONATOR HOSE	Not Necessary	304.00 FL	*- FL
37	1		*FRT RADAR MODULE	Cracked	3,369.00 FL	*3,369.00 FL
38	1		*FRT RADAR MODULE BRACKET	Bent	273.00 FL	*273.00 FL
39	1		*ENGINE ROOM & BODY CHASSIS WIRE HARNESS	Cracked	7,335.00 FL	*7,335.00 FL
40	1		*FRT FORWARD CAMERA	Damaged	852.00 FL	*852.00 FL
41	1		*FRT FORWARD CAMERA BRACKET	Damaged	83.00 FL	*83.00 FL
42	1		*FRT BUMPER LOW CENTRE GRILLE	Cracked	266.00 FL	*266.00 FL
43	1		*FRT NUMBER PLATE	Cracked	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)38,040.5027,207.50

- List Item Discount on L Items 10.00/10.00% (\$\$)3,797.552,714.25

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	34,242.95 24,493.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	3,900.00	1,300.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA, FRT BUMPER, FRT BONNET, FRT SUPORT PANEL, FRT FENDER LH, FRT FENDER RH, FRT DOOR RH, FRT DOOR LH	New	2,750.00	1,375.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	220.00	120.00
4	TO REMOVE AND REFIT AIRCON CONDENSOR,VACUUM,REFILL AND CHECK AIR CON GAS SYSTEM	New	600.00	0.00
5	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	120.00	0.00
6	TO CONDUCT RESET OF ADAS	New	600.00	600.00
7	TO CONDUCT RESET OF ENGINE LIGHT ON	New	350.00	350.00
8	TO REFOCUS HEADLAMP	New	80.00	0.00
9	TO REMOVE AND REFIT FRONT SENSOR	New	120.00	60.00
10	TO REMOVE & REPLACE ENGINE ROOM & BODY CHASSIS WIRE HARNESS	New	5,000.00	3,250.00
Gross Labour Cost (S\$)			13,740.00	7,055.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >