

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22005901/VCY3E2**Date:** 03/01/2023REFERENCE

Insured/Claimant: MANOKARAN S/O VELAYUTHAM Policy No: DMHCSNW00008812200

Date of Loss: 18/06/2022

Nature of Claim: OD

Claim No: SNM22D204283/C01/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNA3394Y**

Make & Model: VOLVO S60, 1.6 D2 (A)

Engine No: D4162T2710352

Reg. Date: 28/05/2014 (Man. Year: 2013)

Chassis No: YV1FS84ABE2302334

Colour: Silver

Odometer: 102678 km

Engine Capacity: 1560 cc

Market Value/New Car Price: S\$37,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18

Rear Tyre Size: 245/40Z R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	1,250.00	-1,250.00	
Nett Amount (S\$)	0.00	-1,250.00	1,250.00	

INSPECTION

Date of Assignment: 21/06/2022

Date Inspected: 21/06/2022

Inspected At:

Blk 14 Defu Lane 10, #01-410/412

Singapore 539195

Repairer: TSL Auto Garage

Estimated Period of Repair: 0.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$37,000.00
OMV :	\$32,298.00
PARF Rebate (1) :	\$12,219.00
Quota Premium Paid :	\$60,002.00
COE Rebate (2) :	\$11,581.00
Total Rebate (1) + (2) = :	\$23,800.00

The total amount incurred will be Market Value \$37,000.00 minus Total Rebate \$23,800.00 = \$13,200.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2023)
Parts:	143	VOLVO S60 1.6 D2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA3394Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >