

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 466X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	BENT	980.00	953.00
1	TAILGATE INNER TRIM	SERVICEABLE	200.00	-
1	TAILGATE LOCK ASSY	JAMMED	120.00	120.00
1	REAR WINDSCREEN MOULDING	NECESSARY	80.00	80.00
1	TAILGATE LAMP RHS	CRACKED	460.00	413.20
1	TAILGATE LAMP LHS	CRACKED	460.00	413.20
1	TAIL LAMP RHS	SERVICEABLE	660.00	-
1	TAIL LAMP LHS	SERVICEABLE	660.00	-
1	HONDA EMBLEM	SERVICEABLE	40.00	-
1	VEZEL EMBLEM	NECESSARY	50.00	50.00
1	REAR BUMPER	BENT	510.00	510.00
1	REAR BUMPER RETAINER RHS	SERVICEABLE	30.00	-
1	REAR BUMPER RETAINER LHS	SERVICEABLE	30.00	-
1	END PANEL	BENT	420.00	420.00
1	END PANEL TOP GARNISH	DENTED	70.00	70.00
1	TAILGATE MOULDING	SERVICEABLE	260.00	-
1	REAR BUMPER REFLECTOR RHS	SERVICEABLE	160.00	-
1	REAR BUMPER REFLECTOR LHS	SERVICEABLE	160.00	-
1	REAR CORNER PANEL RHS	SERVICEABLE	150.00	-
1	REAR CORNER PANEL LHS	SERVICEABLE	150.00	-
1	REAR WHEEL ARCH MOULDING RHS	SERVICEABLE	180.00	-
1	REAR WHEEL ARCH MOULDING LHS	SERVICEABLE	180.00	-
1	EXHAUST	TO REPAIR SEE LABOUR	540.00	-
1	SMART BUZZER	SERVICEABLE	110.00	-
1	KEY ANTENNA	SERVICEABLE	60.00	-
1	SPARE TYRE PANEL SPONGE	CRACKED	260.00	260.00
1	REAR FRAME STIFFENER RHS	SERVICEABLE	100.00	-
1	REAR FRAME STIFFENER LHS	SERVICEABLE	100.00	-
1	REAR BUMPER UNDERCARRIAGE COVER	CRACKED	130.00	130.00

Report Ref No. CS/SMO22005902/Kqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR FENDER RHS	TO REPAIR SEE LABOUR	940.00	-
1	REAR FENDER LHS	TO REPAIR SEE LABOUR	940.00	-
1	REAR FENDER INNER SHIELD RHS	SERVICEABLE	190.00	-
1	REAR FENDER INNER SHIELD LHS	SERVICEABLE	190.00	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	840.00	-
1	REAR FENDER INNER TRIM LHS	MTG CRACKED	300.00	300.00
1	REAR FENDER INNER TRIM RHS	SERVICEABLE	300.00	-
1	TAILGATE WEATHERSTRIPE	DENTED / DISTORTED	110.00	110.00
1	SPARE TYRE TOP COVER	SERVICEABLE	150.00	-
1	WIPER MOTOR	SERVICEABLE	150.00	-
1	SPARE TYRE TOOLS COMPARTMENT	SERVICEABLE	250.00	-
	LESS 20% DISCOUNT		-2,334.00	-765.88
			9,336.00	3,063.52
	SPECIAL NETT ITEMS			
1	REAR SENSORS (SN)	SERVICEABLE	200.00	-
1	CARPLATE W/HOLDER (SN)	SERVICEABLE	40.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
1	SET BUMPER CLIPS (SN)	NECESSARY	60.00	60.00
1	REVERSE CAMERA (SN)	SERVICEABLE	200.00	-
			540.00	100.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF EXHAUST, REAR FENDER RHS, REAR FENDER LHS AND SPARE TYRE PANEL.		1,800.00	600.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		1,800.00	750.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.		100.00	20.00

Report Ref No. CS/SMO22005902/Kqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.		100.00	60.00
	TRANSFER TAILGATE PARTS.		150.00	60.00
	REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	REMOVE & REFIT REAR SENSORS.		100.00	50.00
			4,200.00	1,660.00
	GRAND TOTAL		14,076.00	4,823.52

RECOMMENDED COST OF LUMP SUM REPAIRS		3,850.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/SMO22005902/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser