

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22005903/KNY3E2

Date: 10/08/2022

REFERENCE

Insured/Claimant: Bank of China Limited Policy No: DMB1SNW00005142102

Date of Loss: 20/06/2022

Nature of Claim: OD

Claim No: SNM22D204325/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC7024E**

Make & Model: TOYOTA HIACE, 3.0 D TURBO 4DR (A)

Engine No: 1KD2795955

Reg. Date: 25/04/2018 (Man. Year: 2018)

Chassis No: JTFHT02P600242075

Colour: Silver

Odometer: 111143 km

Engine Capacity: 2982 cc

Market Value/New Car Price: S\$72,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8

Rear Tyre Size: 195 R15X8

Front Left Side: Michelin 9 mm

Rear Left Side: Michelin 9 mm

Front Right Side: Michelin 9 mm

Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,522.00	1,522.00	0.00	0.00
Miscellaneous Items	57.50	57.50	0.00	0.00
Labour	411.60	369.60	42.00	10.20
Paintwork Labour	483.09	483.09	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,474.19	2,432.19	42.00	1.70
- Excess (S\$)	0.00	1,000.00	-1,000.00	
(S\$)	2,474.19	1,432.19	1,042.00	42.11
+ GST 7.00/7.00% (S\$)	173.19	100.25	72.94	42.12
Nett Amount (S\$)	2,647.38	1,532.44	1,114.94	42.11

INSPECTION

Date of Assignment: 21/06/2022 Present Location:

Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

Date Inspected: 22/06/2022 Inspected At:

Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive #04-01, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Aug 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO 4DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC7024E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		1,522.00 F	*1,522.00 F
F=Franchise part.						
Total Parts (S\$)					1,522.00	1,522.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Extra	57.50	57.50
Sub Total (\$\$)			57.50	57.50

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Including Material	New	483.09	483.09
<u>Labour Items</u>				
2	Total of Labour	New	411.60	369.60
Gross Labour Cost (\$\$)			894.69	852.69

Report was unsubmitted during this print-out.

< END OF ESTIMATES >