

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005904/UQY3E2

Date: 14/07/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00011392101  
Claimant Vehicle No: SMM8166E Insured Vehicle No: SLZ3255H  
Date of Loss: 18/06/2022 Nature of Claim: TP Claim No: SNM22D204292/C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM8166E  
Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: LEB7104547  
Reg. Date: 15/07/2019 (Man. Year: 2018) Chassis No: GP72003485  
Colour: Blue Odometer: 37171 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,727.92	2,628.40	1,099.52	29.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,090.00	1,560.00	530.00	25.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,817.92</b>	<b>4,188.40</b>	<b>1,629.52</b>	<b>28.01</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,350.00</b>		
<b>(S\$)</b>	5,817.92	3,350.00	2,467.92	42.42
<b>+ GST 7.00/7.00% (S\$)</b>	407.25	234.50	172.75	42.42
<b>Nett Amount (S\$)</b>	<b>6,225.17</b>	<b>3,584.50</b>	<b>2,640.67</b>	<b>42.42</b>

### INSPECTION

Date of Assignment: 21/06/2022  
Date Inspected: 23/06/2022 Inspected At: Progressive Car Care Pte Ltd (HQ)  
Blk 3022A Ubi Road 1, #01-45/46  
Singapore 408716  
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 Jul 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM8166E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Badly Dented	1,193.00 FL	*1,193.00 FL
2	1		*REAR BOOT GLASS MOULDINGS	Necessary	142.30 FL	*142.30 FL
3	1		*REAR BOOT SHUTTLE WORDINGS	Necessary	59.00 FL	*59.00 FL
4	1		*REAR BOOT H LOGO	Necessary	27.40 FL	*27.40 FL
5	1		*REAR BOOT HYBRID WORDINGS	Necessary	78.00 FL	*78.00 FL
6	2		*REAR BOOT NUMBER PLATE LAMP - LH / RH	Not Necessary	80.20 FL	*- FL
7	1		*REAR BOOT RUBBER	Not Necessary	168.50 FL	*- FL
8	1		*REAR BOOT OUTER CHROME	Not Necessary	383.10 FL	*- FL
9	1		*REAR BOOT TOP LOCK	Not Necessary	138.50 FL	*- FL
10	1		*REAR BOOT BOTTOM LOCK	Not Necessary	28.00 FL	*- FL
11	1		*REAR BUMPER	Dented	1,150.60 FL	*936.00 FL
12	1		*REAR BUMPER SIDE HOLDER - LH	Not Necessary	28.00 FL	*- FL
13	1		*REAR BUMPER SIDE HOLDER - RH	Not Necessary	28.00 FL	*- FL
14	10		*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
15	1		*REAR PANEL	Dented	560.80 FL	*560.80 FL
16	1		*REAR PANEL TOP GARNISH	Not Necessary	155.50 FL	*- FL
17	1		*SET REAR BUMPER SENSOR	Shorted	220.00 FS	*200.00 FS
18	1		*SET REAR NUMBER PLATE WITH CASING	Serviceable	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,579.90	3,235.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	851.98	607.10
Total Parts (\$\$)	3,727.92	2,628.40

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK OUT DENTS, CUT/WELD, REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	New	800.00	600.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	800.00	680.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE, REPLACE REAR BUMPER SENSOR	New	50.00	50.00
5	TO TUFF-KOTE	New	60.00	30.00
6	TO REMOVE, REPLACE REAR BOOT GLASS	New	150.00	120.00
7	TO REMOVE, REFIX REAR GARNISH AND RELATED PARTS	New	100.00	60.00
8	TO REMOVE, REPAIR REAR EXHAUST PIPE	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,090.00</b>	<b>1,560.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >