



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 8070R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR WINDSCREEN SEAL	NOT NECESSARY	95.00	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	4,050.80	-
1	REAR TAILGATE LOCK	NOT NECESSARY	252.20	-
1	REAR TAILGATE LOGO	NOT NECESSARY	156.00	-
1	REAR TAILGATE RUBBER	NOT NECESSARY	247.00	-
1	REAR TAILGATE "2.0" EMBLEM	NOT NECESSARY	98.00	-
1	REAR TAILGATE "QUATTRO" EMBLEM	NOT NECESSARY	95.00	-
2	REAR TAILLAMPS	NOT NECESSARY	2,215.20	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	806.00	-
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	299.00	-
1	REAR KEYLESS SENSOR	NOT NECESSARY	247.00	-
1	REAR BUMPER	DISTORTED	1,324.40	1,324.40
1	REAR BUMPER - LOWER	DISTORTED	426.80	426.80
1	SET REAR BUMPER CLIP	NECESSARY	92.40	50.00
1	REAR BUMPER TOW HOOK COVER	MISSING	52.00	52.00
1	REAR BUMPER REFLECTOR N/S	BROKEN	407.00	305.10
1	REAR BUMPER REINFORCEMENT	BENT	754.00	452.35
1	REAR BUMPER SIDE RETAINER N/S	CRACKED	110.00	92.50
2	REAR BUMPER PDC SENSORS	SHORTED	494.00	364.00
1	REAR FENDER WHEEL ARCH GARNISH - LH	NOT FITTED	233.20	-
	LESS 5% DISCOUNT		-622.75	-153.36
			11,832.25	2,913.79
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
			80.00	-
<b><u>LABOUR</u></b>				
	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING. INCLUSIVE OF THE REPAIR OF REAR TAILGATE AND REAR END PANEL.		80.00	30.00

Report Ref No. CS/AGI22005907/Uvy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT INNER GARNISHES.		150.00	80.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	50.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	TO APPLY UNDERCOATING.	NOT NECESSARY	150.00	-
	PANEL BEATING.		1,400.00	580.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,200.00	600.00
			3,310.00	1,340.00
<b>GRAND TOTAL</b>			<b>15,222.25</b>	<b>4,253.79</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,400.00</b>

Report Ref No. CS/AGI22005907/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.