

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO22005909/Uqy3m4	
	50 RAFFLES PLAC SINGAPORE LAND	E #03-03 O TOWERSINGAPORE 048623		Date:	05/07/2022	
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SFH 3488T	Veh. Inspected		SLC 6466S	
	Policy No.	D22MTPV01004724	Coverage (\$)		0.00	
	Claim No.	CMTD2202120/IJH	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		21/06/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA VIOS (A)	c.c		1497	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	MHFBT9F3506065496	Colour		SILVER	
	Odometer	111480 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/55 R15	RAPID		6 mm	
	L/H Front Tyre	195/55 R15	RAPID		6 mm	
	R/H Rear Tyre	195/55 R15	RAPID		6 mm	
	L/H Rear Tyre	195/55 R15	RAPID		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	5. General Information					
	Accident Date	16/06/2022	Inspect Date / T	Time	27/06/2022 (10:10 AM)	
	Survey held at	WEE HOE AUTO SERVICE				
		19 KIM CHUAN TERRACE SINGAPORE 537041				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,500					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/SMO22005909/Uqy3m4

Inspected By

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser