



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 271D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR REVERSE CAMERA (SN)	SERVICEABLE	300.00	-
1	REAR STEP METAL BAR (SN)	WARPED	150.00	150.00
1	REAR STEP WOODEN BAR (SN)	CRACKED	100.00	100.00
1	REAR WOODEN TAIL GATE (SN)	TO REPAIR SEE LABOUR	1,800.00	-
1	TAIL GATE 60KM/H STICKER (SN)	NECESSARY	15.00	15.00
1	TAIL GATE 24PAX STICKER (SN)	NECESSARY	15.00	15.00
1	TAIL GATE GREEN STICKER (SN)	NECESSARY	20.00	20.00
1	T/GATE STAINLESSSTEEL RIVET (SE) (SN)	NOT NECESSARY	40.00	-
			2,440.00	300.00
	<u>LABOUR</u>			
	TO SPRAY TAIL GATE, END WOODEN PANEL STEP BAR.		600.00	350.00
	TO LIFT UP REAR WOODEN FLOOR FOR ADJUST, ALIGNMENT, REFIX CHASSIS FRAME HOOK AND TIGHTEN WOODEN FLOOR. INCLUSIVE OF THE REPAIR OF REAR WOODEN TAIL GATE.		1,000.00	300.00
			1,600.00	650.00
GRAND TOTAL			4,040.00	950.00
RECOMMENDED COST OF REPAIRS				950.00

Report Ref No. CS/GAI22005911/Kqy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.