

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL	Re	ef:	CS3/SMO22005913/Ucy3e2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623	Da	ate:	06/07/2022	
			Co	ode:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBF 5651H	Veh. Inspected		FV 8082Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2202132/AGC	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		21/06/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	YAMAHA FZ16ST	c.c		153	
	Engine No.	HIDDEN	Year of Reg.		2012	
	Chassis No.	ME145S097C2015730	Colour		YELLOW	
	Odometer	6187 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	100-80-17	PIRELLI		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140-70-17	PIRELLI		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.					
5.	5. General Information					
	Accident Date	16/06/2022	Inspect Date / Tin	ne	24/06/2022 (11:18 AM)	
	Survey held at	25 Kaki Bukit Road 4 #01-43 Syr	nergy @ KB			
	Repairer BLACK INDUSTRY PTE LTD					
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$800-\$900					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/SMO22005913/Ucy3e2

Inspected By

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser