

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005915/UVY3E2

Date: 10/08/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00009252101		
Claimant Vehicle No :	SGZ2999K	Insured Vehicle No :	SML5632B		
Date of Loss:	20/06/2022	Nature of Claim:	TP	Claim No:	SNM22D204327/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGZ2999K	Engine No:	FB20YA98632
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Chassis No:	JF1SJ5KC5JG097932
Reg. Date:	15/09/2017 (Man. Year: 2017)	Odometer:	80884 km
Colour:	Black		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,218.25	13,734.40	6,483.85	32.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,840.00	4,000.00	840.00	17.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,058.25	17,734.40	7,323.85	29.23
+ GST 7.00/7.00% (S\$)	1,754.08	1,241.41	512.67	29.23
Nett Amount (S\$)	26,812.33	18,975.81	7,836.52	29.23

INSPECTION

Date of Assignment:	22/06/2022	
Date Inspected:	22/06/2022	Inspected At: SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	10.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Aug 2022)

Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGZ2999K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT GRILLE TOP (WITH LOGO)	Not Necessary	280.00 FL	*- FL
2	1		*FRT GRILLE LOWER	Cracked	420.00 FL	*420.00 FL
3	4		*GRILLE CLIPS	Not Necessary	34.00 FL	*- FL
4	1		*FRT BUMPER	Dented / Deformed	750.00 FL	*600.00 FL
5	1		*FRT BUMPER RETAINER RH	Necessary	35.00 FL	*35.00 FL
6	10		*FRT BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
7	1		*FRT BUMPER TOW COVER	Missing	35.00 FL	*35.00 FL
8	1		*FRT BUMPER REINFORCEMENT (OUTER)	Dented	280.00 FL	*280.00 FL
9	1		*FRT BUMPER REINFORCEMENT (INNER)	No such part	430.00 FL	*- FL
10	1		*FRT NOZZLE COVER RH	Missing	90.00 FL	*90.00 FL
11	1		*FRT NOZZLE RH	Not Necessary	185.00 FL	*- FL
12	2		*HEADLAMP	Cracked	6,700.00 FL	*6,200.00 FL
13	1		*BRACE PANEL	Not Necessary	125.00 FL	*- FL
14	1		*SUPPORT PANEL FRT GARNISH	Not Necessary	105.00 FL	*- FL
15	4		*GARNISH CLIPS	Not Necessary	22.00 FL	*- FL
16	1		*REAR WINDSCREEN MOULDING	Necessary	55.00 FL	*55.00 FL
17	1		*REAR GATE	Badly Dented	1,450.00 FL	*1,450.00 FL
18	1		*REAR GATE OUTER GARNISH	Cracked	390.00 FL	*390.00 FL
19	1		*REAR GATE LOGO	Not Necessary	105.00 FL	*- FL
20	1		*REAR GATE SUBARU PLATE	Necessary	90.00 FL	*90.00 FL
21	1		*REAR GATE FORESTER PLATE	Necessary	90.00 FL	*90.00 FL
22	1		*REAR GATE AWD PLATE	Necessary	110.00 FL	*110.00 FL
23	1		*REAR GATE SYMMETRICAL PLATE	Necessary	115.00 FL	*115.00 FL
24	1		*REAR GATE LOCK	Dented / Jammed	320.00 FL	*320.00 FL
25	1		*REAR GATE INNER RUBBER	Torn	195.00 FL	*195.00 FL
26	1		*REAR GATE INNER TRIMBOARD	Not Necessary	380.00 FL	*- FL
27	15		*TRIMBOARD CLIPS	Not Necessary	82.50 FL	*- FL
28	1		*REAR BUMPER	Distorted	780.00 FL	*600.00 FL
29	2		*REAR BUMPER RETAINER	Bent	96.00 FL	*96.00 FL
30	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
31	1		*REAR BUMPER REINFORCEMENT	Bent	430.00 FL	*430.00 FL
32	2		*REAR BUMPER REFLECTOR	Not Necessary	110.00 FL	*- FL
33	1		*REAR BUMPER TOW COVER	Torn	45.00 FL	*45.00 FL
34	1		*TAIL LAMP	N/S Cracked / O/S NotNecessary	1,160.00 FL	*444.00 FL
35	1		*REAR END PANEL	Badly Dented	450.00 FL	*450.00 FL
36	1		*REAR END PANEL TOP TRIM	Not Necessary	150.00 FL	*- FL
37	1		*REAR SPARE TYRE FLOOR PANEL	Repair	750.00 FL	*- FL
38	1		*SPARE TYRE TOP COVER	Not Necessary	495.00 FL	*- FL
39	1		*REAR EXHAUST BOX	Bent	950.00 FL	*950.00 FL
40	1		*EXHAUST CHROME FINISHER	Dented	185.00 FL	*185.00 FL
41	1		*REAR EXHAUST CTR PIPE	Bent	1,250.00 FL	*1,250.00 FL
42	3		*REAR EXHAUST RUBBER HOLDER	Necessary	135.00 FL	*135.00 FL
43	1		*FRT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
44	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS
45	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
46	1		*FRT PARKING SENSOR (4PCS TYPE)	Shorted	350.00 FS	*250.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR WINDSCREEN GUM	Necessary	60.00 FS	*40.00 FS
48	1		*REAR GATE SEALANT	Not Necessary	60.00 FS	*- FS
49	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*50.00 FS
50	1		*REAR FLOOR PANEL SEALANT	Not Necessary	60.00 FS	*- FS
51	1		*REAR FLOOR PANEL INSULATOR PADS	Not Necessary	180.00 FS	*- FS
52	1		*REAR RH FENDER INNER COWLING	Torn	68.00 FL	*68.00 FL
53	1		*REAR CROSSMEMBER	Dented	836.00 FL	*836.00 FL
54	2		*REAR FLOOR PANEL SPONGE (SIDES)	Torn	116.00 FL	*116.00 FL
55	1		*REAR FLOOR PANEL SPONGE (CENTRE)	Torn	140.00 FL	*140.00 FL
56	1		*REAR SPARE TYRE SCREW	Bent	21.00 FL	*21.00 FL
57	2		*TAIL LAMP LOWER BRACKET	Cracked	64.00 FL	*64.00 FL
58	1		*REAR BUMPER EXHAUST COVER LH	Distorted	28.00 FL	*28.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	22,342.50	17,023.00
- List Item Discount on L Items 10.00/20.00% (S\$)	2,124.25	3,288.60
Total Parts (S\$)	20,218.25	13,734.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	40.00	30.00
2	REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	TRANSFER REAR GATE COMPONENTS	New	100.00	60.00
4	REMOVE & REFIX REAR BOOT UPHOLSTERY	New	100.00	80.00
5	CAVITY PROTECTION ON AFFECTED AREAS	New	100.00	80.00
6	REMOVE & REFIX FRT & REAR PARKING SENSOR	New	120.00	50.00
7	REMOVE & REFIX REAR EXHAUST WIRH CENTRE PIPE	New	180.00	120.00
8	R&R REAR UNDER CARRIAGE (WITH CROSSMEMBER)	New	350.00	300.00
9	WHEEL ALIGNMENT	New	80.00	60.00
10	LABOUR CHARGE (FRT)	New	500.00	400.00
11	SPRAY PAINTING (FRT)	New	550.00	400.00
12	LABOUR CHARGE (REAR)	New	1,400.00	1,200.00
13	SPRAY PAINTING (REAR)	New	1,200.00	1,100.00
Gross Labour Cost (\$\$)			4,840.00	4,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >