7/26/22, 3:48 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI22005918/KQY3M4

Date: 26/07/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle SHD9046T Insured Vehicle No: SMR3785A

Date of Loss: 18/06/2022 Nature of Claim: TP Claim No: CDMPG22001185

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9046T

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2B67487

Reg. Date: 01/11/2018 (Man. Year: 2018) Chassis No: JTDKB3FUX03076032

Colour: Metallic Pearl White/Red Odometer: 403931 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: LANVIGATOR 8 mm Rear Left Side: Sailun 9 mm
Front Right Side: LANVIGATOR 8 mm Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,044.02	956.07	5,087.95	84.18
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,790.00	680.00	4,110.00	85.80
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calculate	ed Gross Total (S\$)	10,834.02	1,636.07	9,197.95	84.90
Approved Tota	ıl (Overridden) (S\$)		1,300.00		
	(S\$)	10,834.02	1,300.00	9,534.02	88.00
+ G	ST 7.00/7.00% (S\$)	758.38	91.00	667.38	88.00
	Nett Amount (S\$)	11,592.40	1,391.00	10,201.40	88.00

INSPECTION

Date of Assignment: 24/06/2022

Trans-Cab Services Pte Ltd (HQ)

Date Inspected: 22/06/2022 Inspected At: 2 Ang Mo Kio Street 63

Cingapara F60111

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Condition

Donairor's

Amount

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Jul 2022)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SHD9046T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Oty Part No Particulars

NO.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY, FRONT DOOR, RH	Repair	1,300.70 FL	*-FL
2	1		*HINGE ASSY, FRONT DOOR, LOWER RH	Repair	110.60 FL	*- FL
3	1		*HINGE ASSY, FRONT DOOR, UPPER RH	Repair	97.50 FL	*- FL
4	1		*TAPE, BLACK OUT, NO.1 FRT RH	Not Necessary	13.30 FL	*- FL
5	1		*TAPE, BLACK OUT, NO.2 FRT RH	Not Necessary	43.50 FL	*- FL
6	1		*TAPE, BLACK OUT, NO.3 FRT RH	Not Necessary	26.30 FL	*- FL
7	1		*WEATHERSTRIP, FRONT DOOR, RH	Serviceable	231.30 FL	*- FL
8	1		*FENDER SUB-ASSY, FRONT LH	Bent	977.80 FL	*977.80 FL
9	1		*LINER, FRONT FENDER, LH	Distorted	210.30 FL	*210.30 FL
10	1		*RIM	Serviceable	1,900.10 FL	*- FL
11	1		*HUB CAP	Serviceable	211.50 FL	*- FL
12	1		*ABSORBER ASSY, SHOCK, FRONT RH	Serviceable	472.30 FL	*- FL
13	1		*KNUCKLE, STEERING, RH	Serviceable	663.40 FL	*- FL
14	1		*ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	Serviceable	760.10 FL	*- FL
15	1		*CLIP(FOR FRONT DOOR TRIM BOARD)	Not Necessary	65.00 FS	*-FS
16	1		*FRT DOOR STICKER TRANSCAB	Not Necessary	100.00 FS	*-FS
17	1		*FRT DOOR ADVERTISEMENT	Not Necessary	200.00 FS	*-FS
18	1		*TYRE	Serviceable	350.00 FS	*-FS
19	1		*FENDER LINER CLIP	Necessary	65.00 FS	*65.00 FS
F=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	7,798.70	1,253.10
	- List Item Discount on L Items 25.00/25.00% (S\$)				1,754.68	297.03
				Total Parts (S\$)	6,044.02	956.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
<u>Lab</u>	our Items					
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	30.00		
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	440.00		
3	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS, AND OTHER, TO ENABLE REPAIR	New	380.00	0.00		
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00		
5	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,800.00	200.00		
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00		
7	TO TRANSFER OF REAR FENDER PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00		
	Gross Labou	r Cost (S\$)	4,790.00	680.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >