

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22005921/APA3Q2**Date:** 02/02/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MPC0006458_2
Claimant Vehicle No : SMA3280D **Insured Vehicle No :** SKX1819S
 Date of Loss: 20/06/2022 Nature of Claim: TP Claim No: MPC2022D0003186

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA3280D**
 Make & Model: SUBARU FORESTER, 2.0 I-L CVT AWD SR (A) Engine No: FB20YD95131
 Reg. Date: 22/06/2018 (Man. Year: 2018) Chassis No: JF1SJ5KC5JG110337
 Colour: Black Odometer: 104119 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,037.92	6,423.28	4,614.64	41.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,590.00	2,820.00	3,770.00	57.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,627.92	9,243.28	8,384.64	47.56
Approved Total (Overridden) (S\$)		7,400.00		
Nett Amount (S\$)	17,627.92	7,400.00	10,227.92	58.02
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		38.45		
Nett Liability (S\$)		8,238.45		

INSPECTION

Date of Assignment: 21/06/2022
 Date Inspected: 22/06/2022 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Dec 2022)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA3280D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,390.00 FL	*1,390.00 FL
2	1		*TAILGATE OUTER MOULDING	Cracked	358.00 FL	*358.00 FL
3	1		*TAILGATE EMBLEM SUBARU	Necessary	82.40 FL	*82.40 FL
4	1		*TAILGATE EMBLEM AWD	Necessary	62.10 FL	*62.10 FL
5	1		*TAILGATE EMBLEM FORESTER	Necessary	72.30 FL	*72.30 FL
6	1		*TAILGATE INNER LOCK	Damaged	560.00 FL	*285.00 FL
7	1		*TAILGATE LOWER LOCK	Not Necessary	30.40 FL	*- FL
8	2		*TAILGATE STOPPER	Not Necessary	38.00 FL	*- FL
9	1		*TAILGATE WEATHERSTRIP	Cut	170.00 FL	*170.00 FL
10	1		*TAILGATE INNER TRIM(LOWER)	Cracked	280.40 FL	*280.40 FL
11	1		*TAILGATE WINDSCREEN C/W MOULDING	Necessary	1,250.00 FL	*185.00 FL
12	1		*REAR BUMPER	Deformed	680.00 FL	*680.00 FL
13	1		*REAR BUMPER TOWING COVER	Deformed	24.30 FL	*24.30 FL
14	1		*REAR BUMPER REFLECTOR	N/S Cracked	84.00 FL	*42.00 FL
15	1		*REAR BUMPER REINFORCEMENT	Dented	396.80 FL	*396.80 FL
16	2		*REAR BUMPER SIDE RETAINER	Necessary	72.00 FL	*72.00 FL
17	1		*REAR BUMPER EXHAUST COVER	Deformed	24.40 FL	*24.40 FL
18	2		*TAILLAMP C/W BRACKET	Cracked	950.00 FL	*950.00 FL
19	2		*REAR FENDER INNER COWLING	Not Necessary	230.00 FL	*- FL
20	1		*REAR FENDER INNER TRIM	N/S Cracked	596.00 FL	*298.00 FL
21	1		*REAR END PANEL	Dented	460.00 FL	*460.00 FL
22	1		*REAR END PANEL TOP GARNISH	Deformed	135.00 FL	*135.00 FL
23	1		*REAR SPARE TYRE BOLT	Damaged	29.00 FL	*29.00 FL
24	1		*REAR FLOOR PANEL	Buckled	1,145.00 FL	*832.00 FL
25	1		*REAR TOOL TRAY	Not Necessary	178.00 FL	*- FL
26	1		*REAR FLOOR PANEL TOP TRAY (SPONGE)	Cracked	180.00 FL	*180.00 FL
27	2		*REAR FLOOR PANEL SIDE SPONGE	Cracked	150.00 FL	*150.00 FL
28	1		*REAR FLOOR PANEL TOP BOARD	Deformed	320.40 FL	*320.40 FL
29	1		*REAR FLOOR PANEL TOP BOARD (INNER SUPPORT)	Not Necessary	375.00 FL	*- FL
30	2		*REAR FLOOR PANEL TOP SIDE BOARD	Not Necessary	121.00 FL	*- FL
31	1		*REVERSE CAMERA	Not Necessary	690.40 FL	*- FL
32	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
33	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
34	1		*SET TAILLAMP CLIP	Necessary	30.00 FS	*30.00 FS
35	1		*SET TAILGATE OUTER MOULDING CLIP	Necessary	30.00 FS	*20.00 FS
36	1		*SET TAILGATE INNER TRIM (LOWER) CLIP	Necessary	60.00 FS	*30.00 FS
37	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
38	1		*TAILGATE WINDSCREEN INNER SHIELD	Not Necessary	60.00 FS	*- FS
39	1		*TAILGATE WINDSCREEN SOLAR FILM	Not Necessary	550.00 FS	*- FS
40	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
41	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*10.00 FS
42	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
43	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
44	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)13,264.907,919.10

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					2,226.98	1,495.82
Total Parts (S\$)					11,037.92	6,423.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT REMOVE AND REPLACE PARTS	New	2,500.00	1,200.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	1,000.00
3	TUFF COAT	New	250.00	120.00
4	WIRING AND BULB CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	120.00
6	REMOVE AND REFIX VIDEO CAMERA	New	80.00	50.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
9	REAR CHASSIS ALIGNMENT	New	250.00	0.00
10	TRANFER TAILGATE MECHANISM	New	80.00	80.00
11	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
12	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
13	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
14	REMOVE AND REFIX FUEL TANK	New	120.00	0.00
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	600.00	0.00
Gross Labour Cost (S\$)			6,590.00	2,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >