

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNE 8640H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HEADLAMP RH (CONSISTENT)	BROKEN	4,967.00	4,967.00
1	HEADLAMP WASHER JET RH (CONSISTENT)	NOT NECESSARY	125.00	-
1	HEADLAMP WASHER JET COVER RH (CONSISTENT)	NOT NECESSARY	41.00	-
1	FRONT BUMPER (CONSISTENT)	DENTED	1,514.00	1,514.00
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	BROKEN	38.00	38.00
10	FRONT BUMPER CLIPS @\$3.00(CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT FENDER RH (CONSISTENT)	DENTED	635.00	635.00
1	FRONT FENDER COWLING RH (CONSISTENT)	NOT NECESSARY	154.00	-
10	FRONT FENDER COWLING CLIPS @\$3.00(CONSISTENT)	NOT NECESSARY	30.00	-
1	HORN (CONSISTENT)	NOT NECESSARY	170.00	-
1	FOG LAMP COVER RH (CONSISTENT)	NOT NECESSARY	137.00	-
1	HEADLAMP ECU (CONSISTENT) (ADDITIONAL)	SHORTED	641.00	641.00
2	NUT PLUG FENDER RH @\$8.00 (CONSISTENT) (ADDITIONAL)	NECESSARY	16.00	16.00
	LESS 5% DISCOUNT		-424.90	-392.05
			8,073.10	7,448.95
	SPECIAL NETT ITEMS			
1	PROGRAMMING HEADLAMP ECU (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	300.00	300.00
			300.00	300.00
	<u>LABOUR</u>			
	TO INSPECT FRONT LIGHTING MECHANISM & CHECK WIRING .		80.00	50.00
	TO REMOVE & REPLACE DAMAGED ITEMS ,REALIGN CONNECTION .		500.00	400.00
	TO SPRAY PAINT ON REPAIRED AREAS .		500.00	400.00
			1,080.00	850.00
	GRAND TOTAL		9,453.10	8,598.95

Report Ref No. CC4/ASM22005928/Epa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	7,750.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CC4/ASM22005928/Epa3q2



Automotive Assessor

Amont

HO LEONG CHUAN

Automotive Assessor