

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIS22005940/DNY3Q2**Date:** 17/10/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SPMF1000000509  
**Claimant Vehicle No :** SMH3484X **Insured Vehicle No :** SMA7053S  
 Date of Loss: 19/06/2022 Nature of Claim: TP Claim No: C88AISCL2022-0007FR

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH3484X**  
 Make & Model: HONDA CIVIC, VTI-L 1.6 Engine No: R16A13005196  
 Reg. Date: 09/06/2008 (Man. Year: 2008) Chassis No: JHMFD46208S201710  
 Colour: Grey Odometer: 295414 km  
 Engine Capacity: 1595 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17  
 Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm  
 Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,909.36	1,730.84	13,178.52	88.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,840.00	1,050.00	4,790.00	82.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,749.36</b>	<b>2,780.84</b>	<b>17,968.52</b>	<b>86.60</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,200.00</b>		
<b>(S\$)</b>	20,749.36	2,200.00	18,549.36	89.40
<b>+ GST 7.00/7.00% (S\$)</b>	1,452.46	154.00	1,298.46	89.40
<b>Nett Amount (S\$)</b>	<b>22,201.82</b>	<b>2,354.00</b>	<b>19,847.82</b>	<b>89.40</b>

INSPECTION

Date of Assignment: 22/06/2022  
 Date Inspected: 22/06/2022 Inspected At: C.s.ong Auto Pte Ltd (HQ)  
 10, ANG MO KIO IND PARK 2A #02-16 AMK  
 AUTO POINT SINGAPORE 568047  
 Singapore 568047  
 Estimated Period of Repair: 3.0 days

**Adjuster:** BRYAN TANI**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2022)	
<b>Parts:</b> 143	HONDA CIVIC VTI-L 1.6 (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b> (Unsubmitted, no print-code for SMH3484X)		
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Repair	937.50 FL	*- FL
2	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	194.80 FL	*- FL
3	1		*HEAD LAMP RH	Broken	1,412.10 FL	*894.80 FL
4	1		*HEAD LAMP LOWER BRACKET RH	Not Necessary	199.10 FL	*- FL
5	2		*FRONT BUMPER SIDE RETAINER LH/RH	Serviceable	124.40 FL	*- FL
6	1		*WIPER WASHER TANK	Not Necessary	317.00 FL	*- FL
7	1		*WIPER WASHER TANK MOTOR	Not Necessary	482.00 FL	*- FL
8	1		*FRONT WHEEL BEARING RH	Not Necessary	342.60 FL	*- FL
9	1		*FRONT WHEEL BEARING HUB RH	Not Necessary	379.60 FL	*- FL
10	1		*FRONT ABSORBER RH	Not Necessary	634.30 FL	*- FL
11	1		*FRONT LOWER ARM RH	Not Necessary	505.10 FL	*- FL
12	1		*FRONT KNUCKLE ARM RH	Not Necessary	543.10 FL	*- FL
13	1		*FRONT STABILIZER LINK RH	Not Necessary	196.90 FL	*- FL
14	1		*FRONT STABILIZER BAR	Not Necessary	289.40 FL	*- FL
15	1		*FRONT TIE ROD RH	Not Necessary	298.70 FL	*- FL
16	1		*FRONT TIE ROD END RH	Not Necessary	387.10 FL	*- FL
17	1		*STEERING RACK & PINION ASSY	Not Necessary	2,980.00 FL	*- FL
18	1		*DRIVE SHAFT RH	Not Necessary	2,481.00 FL	*- FL
19	1		*FRONT GRILLE RED LOGO	Not Necessary	182.00 FL	*- FL
20	1		*FRONT BUMPER	Cut / Mtg Broken	2,200.00 FS	*1,000.00 FS
21	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*15.00 FS
22	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*FRONT BUMPER LOWER SKIRTING	Not Necessary	1,500.00 FS	*- FS
24	1		*FRONT RIM RH	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>17,486.70</b>	<b>1,909.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	2,577.34	178.96
<b>Total Parts (\$\$)</b>	<b>14,909.36</b>	<b>1,730.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	400.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	400.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	20.00
5	TO RNR FRONT UNDERCARRIAGE SYSTEM TO FACILITATE REPAIRS	New	400.00	0.00
6	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	0.00
7	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
8	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
9	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	0.00
			<b>Gross Labour Cost (\$)</b>	<b>5,840.00</b>
				<b>1,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >