

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005941/EVY3E2

Date: 12/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00245482101
Claimant Vehicle No: SLU9610C Insured Vehicle No: SLJ3281R
Date of Loss: 11/06/2022 Nature of Claim: TP Claim No: SNM22D204116/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU9610C**
Make & Model: HONDA SHUTTLE, 1.5 (A) Engine No: LEB6326388
Reg. Date: 19/12/2017 (Man. Year: 2017) Chassis No: GP71121398
Colour: Silver Odometer: 78849 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,945.00	2,055.00	1,890.00	47.91
Miscellaneous Items	335.00	260.00	75.00	22.39
Labour	840.00	617.40	222.60	26.50
Paintwork Labour	372.79	353.25	19.54	5.24
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,492.79	3,285.65	2,207.14	40.18
+ GST 7.00/7.00% (\$\$)	384.50	230.00	154.50	40.18
Nett Amount (\$\$)	5,877.29	3,515.65	2,361.64	40.18

INSPECTION

Date of Assignment: 22/06/2022 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)
Date Inspected: 22/06/2022 Inspected At: Auto Insure Pte Ltd (HQ) (Woodlands)
6 Marsiling Lane
Singapore 739145
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Jul 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU9610C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		3,945.00 F	*2,055.00 F
F=Franchise part.						
Total Parts (\$\$)					3,945.00	2,055.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	335.00	260.00
Sub Total (\$\$)			335.00	260.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR FOR SPRAY PAINTING	New	372.79	353.25
<u>Labour Items</u>				
2	LABOUR FOR PANEL BEATING	New	827.40	617.40
3	LABOUR FOR RUST PROOFING	New	12.60	0.00
Gross Labour Cost (\$\$)			1,212.79	970.65

Report was unsubmitted during this print-out.

< END OF ESTIMATES >