7/26/22, 11:03 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005944/KCY3M4

26/07/2022 Date:

REFERENCE

China Taiping Insurance (Singapore) Handling Insurer:

Policy No:

DMPCSNA00041162201

Claimant Vehicle

Pte. Ltd.

Insured Vehicle

No:

GBG674U

No:

SDM2211D

Date of Loss:

20/06/2022

Nature of Claim: TP Claim

SNM22D204303/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBG674U Reg No:

Make & Model:

NISSAN NV350, 2.5 PANEL VAN 5MT 5DR EURO V

Engine No: YD25416955A

Reg. Date:

30/05/2017 (Man. Year: 2016)

JN1MC2E26Z0008008 Chassis No:

No:

Colour: Silver

Odometer:

184374 km

Engine Capacity:

2488 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 195 R15X8 Rear Tyre Size:

Front Left Side: Triangle 9 mm Rear Left Side: GREEN-MAX 2 mm Front Right Side: Rear Right Side: GREEN-MAX 2 mm Triangle 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|-----------------------------------|------------|------------|---|--------|
| Parts | | 2,400.10 | 1,913.29 | 486.81 | 20.28 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 1,350.00 | 820.00 | 530.00 | 39.26 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Calculated Gross Total (S\$) | 3,750.10 | 2,733.29 | 1,016.81 | 27.11 |
| | Approved Total (Overridden) (S\$) | | 2,150.00 | 0.00 0.00 1,016.81 1,600.10 112.01 | 42.67 |
| | (S\$) | 3,750.10 | 2,150.00 | | |
| | + GST 7.00/7.00% (S\$) | 262.51 | 150.50 | 112.01 | 42.67 |
| | Nett Amount (S\$) | 4,012.61 | 2,300.50 | 1,712.11 | 42.67 |

INSPECTION

Date of Assignment: 22/06/2022

Falcon-Air Auto Services Pte Ltd (Sin Ming) Date Inspected: 27/06/2022 Inspected At:

176 Sin Ming Drive #01-06, Sin Ming Autocare

Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: **CELINE FONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

REPAIR DETAILS

7/26/22, 11:03 AM

| Reference | | | | |
|--|--|---|--|--|
| Part Source: | | (Last Synchronised: 26 Jul 2022) | | |
| Parts: | N/A | NISSAN NV350 2.5 PANEL VAN 5MT 5DR EURO V (M) (Model not available in database) | | |
| Labour: | Repairer's | (Price-denominated Standard List) | | |
| Print Code: | (Unsubmitted, no print-code for GBG674U) | | | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | | | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | | | | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------|-------------|--|----------------|------------|------------|
| 1 | 1 | | *LH HEADLAMP | Cut | 430.60 F | *430.60 FN |
| 2 | 1 | | *LH FRONT CORNER PANEL | Bent | 534.60 F | *534.60 FN |
| 3 | 1 | | | Mtg Cracked | 571.90 F | *571.90 FN |
| 4 | 1 | | *LH FRONT BUMPER SIDE RETAINER | Cracked | 181.00 F | *181.00 FN |
| 5 | 14 | | *FRONT BUMPER CLIP | Necessary | 42.00 FS | *42.00 FS |
| 6 | 1 | | *LH FRONT DOOR COMPANY NAME STICKER | Necessary | 40.00 FS | *25.00 FS |
| 7 | 1 | | *LH FRONT DOOR COMPANY LOGO, DOOR WRAP AND STEP PANEL WRAP | Necessary | 600.00 FS | *300.00 FS |
| F=Fra | ınchise | part. S=9 | SpcNett. N=NettItemDisc. Sul | b Total (S\$) | 2,400.10 | 2,085.10 |
| | | | - Nett Item Discount on N Items 0.00/1 | | • | 171.81 |
| | | | Tota | l Parts (S\$) | 2,400.10 | 1,913.29 |
| | | | Report was unsubmitted during this print-out. | | | |

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount | |
|---|---|------------|------------|--------|--|
| Lab | our Items | | | | |
| 1 | TO FOCUS HEADLAMP | New | 50.00 | 20.00 | |
| 2 | TO REPAIR LH FRONT DOOR PILLAR INCLUDING REPLACEMENT OF PARTS | New | 450.00 | 300.00 | |
| 3 | TO SPRAY PAINT ON LH FRONT DOOR, LH FRONT DOOR PILLAR, LH FRONT CORNER PANEL, FRONT BUMPER | New | 850.00 | 500.00 | |
| | Gross Labour | Cost (S\$) | 1,350.00 | 820.00 | |
| Report was unsubmitted during this print-out. | | | | | |

< END OF ESTIMATES >