

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI22005947/VVY3E2

**Date:** 30/08/2022

### REFERENCE

Insured/Claimant: HWA SENG BUILDER PTE LTD Policy No: DMFG22005170  
Date of Loss: 20/06/2022 Nature of Claim: OD Claim No: CDMFG22001192

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ1728B**  
Make & Model: KIA K2500, 2.5 D 6M/T (M) Engine No: D4CBJ699407  
Reg. Date: 24/01/2019 (Man. Year: 2018) Chassis No: KNCSJX76LK7327553  
Colour: White Odometer: 112474 km  
Engine Capacity: 2497 cc  
Market Value/New Car Price: S\$49,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C  
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,535.60	551.10	984.50	64.11
Miscellaneous Items	40.00	30.00	10.00	25.00
Labour	630.00	420.00	210.00	33.33
Paintwork Labour	450.00	400.00	50.00	11.11
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,655.60</b>	<b>1,401.10</b>	<b>1,254.50</b>	<b>47.24</b>
<b>- Excess (S\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>2,155.60</b>	<b>901.10</b>	<b>1,254.50</b>	<b>58.20</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>150.89</b>	<b>63.08</b>	<b>87.81</b>	<b>58.19</b>
<b>Nett Amount (S\$)</b>	<b>2,306.49</b>	<b>964.18</b>	<b>1,342.31</b>	<b>58.20</b>

### INSPECTION

Date of Assignment: 22/06/2022 Present Location: Kan Fook Sing Motor Workshop (Defu)  
Date Inspected: 24/06/2022 Inspected At: Kan Fook Sing Motor Workshop (Defu)  
Estimated Period of Repair: 4.0 days No. 61 Defu Lane 12  
Singapore 539147

**Adjuster:** Thevan Thomas Karthikesavan

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 30 Aug 2022)	
<b>Parts:</b>	N/A	KIA K2500 2.5 D 6M/T (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBJ1728B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*FRONT BONNET</b> (WCP)	Dented	175.00 F	*160.00 F
2	1		<b>*FRONT BONNET LOCK</b> (WCP)	Serviceable	20.00 F	*- F
3	1		<b>*FRONT BONNET EMBLEM</b> (WCP)	Necessary	35.00 F	*40.00 F
4	1		<b>*FRONT GRILLE</b> (WCP)	Serviceable	115.00 F	*- F
5	1		<b>*FRONT HEADLAMP RH</b> (WCP)	Serviceable	165.00 F	*- F
6	1		<b>*FRONT HEADLAMP LH</b> (WCP)	Serviceable	165.00 F	*- F
7	1		<b>*FRONT BUMPER</b> (WCP)	Cut	150.00 F	*150.00 F
8	1		<b>*FRONT BUMPER REINFORCEMENT</b> (WCP)	Serviceable	140.00 F	*- F
9	1		<b>*FRONT BUMPER LOWER GRILLE TOP</b> (WCP)	Cut	28.00 F	*28.00 F
10	1		<b>*FRONT BUMPER LOWER GRILLE LOWER</b> (WCP)	Cut	28.00 F	*28.00 F
11	1		<b>*FRONT BUMPER FOGLAMP COVER LH</b> (WCP)	Missing	15.00 F	*15.00 F
12	10		<b>*FRONT BUMPER CLIP</b> (WCP)	Necessary	25.00 F	*25.00 F
13	1		<b>*FRONT NUMBER PLATE GARNISH</b> (WCP)	Broken	15.00 F	*15.00 F
14	1		<b>*FRONT WIPER PANEL</b> (WCP)	Serviceable	165.00 F	*- F
15	1		<b>*WASHER TANK</b> (WCP)	Deformed	130.00 F	*40.00 F
16	1		<b>*SPARE TANK</b> (WCP)	Serviceable	25.00 F	*- F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>1,396.00</b>	<b>501.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	139.60	50.10
<b>Total Parts (\$\$)</b>	<b>1,535.60</b>	<b>551.10</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	FRONT NUMBER PLATE (BENT)	40.00	30.00
Sub Total (\$\$)			40.00	30.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	SPRAYPAINTING CHARGES	New	450.00	400.00
<u>Labour Items</u>				
2	TO CHECK WIRING SYSTEM	New	50.00	20.00
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	580.00	400.00
Gross Labour Cost (\$\$)			1,080.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >