

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS22005948/UNY3E2

Date: 28/07/2022

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2001659180
Claimant Vehicle No: SLB6553D Insured Vehicle No: SML1348Z
Date of Loss: 19/06/2022 Nature of Claim: TP Claim No: 202222005308KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB6553D
Make & Model: CITROEN C4, 1.6 (A) Engine No: 10JBHD3027713
Reg. Date: 18/04/2016 (Man. Year: 2015) Chassis No: VF73DBHZTFJ863149
Colour: White Odometer: 179999 km
Engine Capacity: 1560 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm
Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,814.00	7,517.70	13,296.30	63.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,830.00	1,360.00	1,470.00	51.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,644.00	8,877.70	14,766.30	62.45
Approved Total (Overridden) (S\$)		7,100.00		
(S\$)	23,644.00	7,100.00	16,544.00	69.97
+ GST 7.00/7.00% (S\$)	1,655.08	497.00	1,158.08	69.97
Nett Amount (S\$)	25,299.08	7,597.00	17,702.08	69.97

INSPECTION

Date of Assignment: 22/06/2022

Date Inspected: 22/06/2022 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2022)
Parts:	144	CITROEN C4 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB6553D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted / Torn	1,680.00 F	*1,108.00 FL
2	1		*FRONT BUMPER CENTRE GRILLE	Torn	525.00 F	*385.00 FL
3	1		*FRONT BUMPER CENTRE PAD	Deformed	880.00 F	*600.00 FL
4	1		*FRONT BUMPER LOGO	Not Necessary	60.00 F	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	No such part	166.00 F	*- FL
6	1		*FRONT BUMPER BEAM	Bent	625.00 F	*505.00 FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
8	1		*FRONT BUMPER LAMP O/S	Cracked	825.00 F	*250.00 FL
9	1		*FRONT BUMPER FOG LAMP O/S	Cracked	399.00 F	*280.00 FL
10	1		*FRONT GRILLE	Not Necessary	825.00 F	*- FL
11	1		*FRONT GRILLE CHROME MOULDING	Not Necessary	455.00 F	*- FL
12	1		*FRONT GRILLE INNER	Cracked	485.00 F	*180.00 FL
13	2		*HEADLAMPS	Holder Cracked	4,840.00 F	*1,960.00 FL
14	1		*HEADLAMP CHROME MOULDING O/S	Cracked	155.00 F	*105.00 FL
15	1		*FRONT SUPPORT PANEL ASSY	Cracked	1,125.00 F	*680.00 FL
16	1		*AIR CON FAN ASSY	Not Necessary	980.00 F	*- FL
17	1		*AIR CON CONDENSER	Not Necessary	850.00 F	*- FL
18	1		*FRONT FENDER O/S	Buckled	1,015.00 F	*755.00 FL
19	1		*FRONT FENDER INNER SHIELD O/S	Not Necessary	299.00 F	*- FL
20	1		*FRONT INTER COOLER	Bent / Punctured	1,800.00 F	*1,100.00 FL
21	1		*FRONT INTER COOLER BRACKET	Cracked	280.00 F	*105.00 FL
22	1		*FRONT INTER COOLER GARNISH	Distorted	455.00 F	*290.00 FL
23	1		*BONNET	Repair	1,960.00 F	*- FL
24	1		*FRONT LICENCE PLATE	Not Necessary	50.00 FS	*- FS
25	1		*BOL RADIATOR COOLANT	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,814.00	8,353.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	835.30
Total Parts (\$\$)	20,814.00	7,517.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO RESET & DIAGNOSTIC SYSTEM	New	180.00	0.00
3	TO DISMANTLE & REFIX REAR EXHAUST	New	180.00	0.00
4	TO REFILL AIR CON GAS	New	100.00	100.00
5	TO SPRAY RUST PROOFING	New	120.00	40.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,000.00	600.00
7	TO PUTTY & SPRAY PAINTING	New	1,200.00	600.00
Gross Labour Cost (\$\$)			2,830.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >