

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005949/EVY3M4**Date:** 25/07/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00107932101

Claimant Vehicle No : SLP3510Z**Insured Vehicle No :** GBK5292J

Date of Loss: 17/06/2022

Nature of Claim: TP

Claim No: SNM22D204289/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLP3510Z**

Make & Model: KIA NIRO, 1.6 HYBRID GDI DCT SUNROOF (A)

Engine No: G4LEHS212577

Reg. Date: 01/06/2017 (Man. Year: 2017)

Chassis No: KNACC81CVH5079489

Colour: Grey

Odometer: 98885 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,252.00	2,631.00	1,621.00	38.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,200.00	2,930.00	1,270.00	30.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	8,452.00	5,561.00	2,891.00	34.20
+ GST 7.00/7.00% (\$\$)	591.64	389.27	202.37	34.20
Nett Amount (\$\$)	9,043.64	5,950.27	3,093.37	34.20

INSPECTION

Date of Assignment: 22/06/2022

Date Inspected: 24/06/2022 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Jul 2022)	
Parts:	N/A	KIA NIRO 1.6 HYBRID GDI DCT SUNROOF (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP3510Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER UPR	Broken	632.00 FS	*632.00 FS
2	1		*COVER ASSY-FR BUMPER LWR	Broken	346.00 FS	*346.00 FS
3	1		*LOGO ASSY-KIA SUB	Necessary	61.00 FS	*61.00 FS
4	1		*STRIP ASSY-FR BUMPER UPR	Not Necessary	38.00 FS	*- FS
5	1		*GRILLE ASSY-RADIATOR	Not Necessary	441.00 FS	*- FS
6	1		*PIECE-FRT BUMPER GUARD LWR, LH	Broken	16.00 FS	*16.00 FS
7	1		*PIECE-FRT BUMPER GUARD LWR, RH	Not Necessary	16.00 FS	*- FS
8	1		*DUCT ASSY-AIR CURTAIN,LH	Not Necessary	32.00 FS	*- FS
9	1		*AIR DUCT-FR BUMPER,LH	Broken	39.00 FS	*39.00 FS
10	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	68.00 FS	*- FS
11	1		*GRILLE-FRONT BUMPER	Not Necessary	232.00 FS	*- FS
12	1		*BRACKET-FR BUMPER SIDE,LH	Broken	12.00 FS	*12.00 FS
13	1		*LAMP ASSY-FRONT FOG & DRL,LH	Not Necessary	638.00 FS	*- FS
14	1		*PANEL-FENDER,LH	Dented	435.00 FS	*435.00 FS
15	1		*GUARD ASSY-FRONT WHEEL,LH	Not Necessary	126.00 FS	*- FS
16	1		*GARNISH ASSY-FNDR SIDE,LH	Broken	123.00 FS	*123.00 FS
17	1		*LAMP ASSY-HEAD,LH	Cut	937.00 FS	*937.00 FS
18	1		*BRACKET-FR BUMPER SIDE MTG, LH	Broken	10.00 FS	*10.00 FS
19	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
					Total Parts (S\$)	4,252.00 2,631.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FR BUMPER & LHF FENDER	New	1,920.00	1,280.00
2	RESPRAY FR BUMPER & LHF FENDER	New	1,650.00	1,100.00
3	CHECK WIRING ELECTRICAL SYSTEM	New	80.00	80.00
4	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
5	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	40.00
6	TOWING BY KING DOLLEY FROM UPPER CHANGI RD. TO C&C P.G.	New	150.00	150.00
Gross Labour Cost (S\$)			4,200.00	2,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >