

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE I	PTE LTD	Ref:	CS3/ASM22005950/Rcy3m4	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	29/06/2022	
	ATTN: LOW GARN	ET	Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 8483B	Veh. Inspected	SKZ 2172G	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	S2M044UJ	Excess (\$)	0.00	
	Assign From	LOW GARNET	Assign Date	22/06/2022	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ E250 SEDAN S/R	c.c	1991	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	WDD2120362B240108	Colour	GREY	
	Odometer	186653 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	245/40 R18	GOODYEAR	6 mm	
	L/H Front Tyre	245/40 R18	GOODYEAR	6 mm	
	R/H Rear Tyre	245/40 R18	GOODYEAR	6 mm	
	L/H Rear Tyre	245/40 R18	GOODYEAR	6 mm	
4. Description of Damages					
	THE VEHICLE SUS	USTAINED DAMAGES AT THE N/S FRONT PORTION.			
5.	5. General Information				
	Accident Date	21/06/2022	Inspect Date / Time	23/06/2022 (02:47 PM)	
	Survey held at 14 AMK ST 63 BIOCK B SINGAPORE 569116				
	Repairer ASSURE AUTO ASSIST PTE LTD				
5a.					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM22005950/Rcy3m4

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser