

ASS. REC. BY:

REF:

C93/SMR22005950/Vqy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBL1775D Yr Regn: 30/03/2021

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA HIACE C.C. 2754Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 29703 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GDH2012017078

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/80 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Danfosh

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. _____ D.O.I. 22/06/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>Submit</u>	<u>US to 4750, 5 days (Red & 2000, 32%)</u>

Date/Time, File Pass to?

☐ : Prell. Report1) 05/09/2022☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____) S + RS. SI☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: TPLump Sum / I.B.A. / 25

U.T APPRAISAL
UNI TEAM (SERVICES) PTE LTD

Email: Uniteam.ops@gmail.com Tel: 91903920

CS3/SMF22005959/vay3

Our Reference: 2206/MEC/1006

Vehicle Reg No: GBL1775D

Remarks

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have neither given authorization nor instruction to the repairer to proceed with the repairs.

Recommendations

Having inspected the actual damages found on the vehicle, we have listed the detailed breakdown of our findings and recommendations.

Under normal circumstances, repairs will take approximately

5
9(NINE)

working days to complete.

The repairer has agreed to undertake this job at a LUMP SUM BASIS of

\$6,250.00

5050



Tay Guang Xiang
Uni Team (Services) Private Limited

U.T APPRAISAL
UNI TEAM (SERVICES) PTE LTD
 Email: Uniteam.ops@gmail.com Tel: 91903920

Our Reference: 2206/MEC/1006

Vehicle Reg No: GBL1775D

Annex B.1

REPLACEMENT PARTS LIST

No.	Qty	Description	Condition	Repairer's Estimation	Revised Amount
1	1	Tailgate	Dent	\$ 1,450.00	\$ 1,450.00
2	1	Tailgate Inner Trimboard	Cut	\$ 419.70	\$ 419.70 <i>Sm</i>
3	1	Tailgate Outer Moulding	Reuse	\$ 155.00	\$
4	1	Tailgate Logo	Necessary	\$ 75.00	\$ 75.00
5	1	Tailgate Lock	Malfunction	\$ 305.00	\$ 305.00 <i>75</i>
6	1	Tailgate Lock Striker	Reuse	\$ 50.00	\$
7	1	Tailgate Lock Cover	Cut	\$ 115.00	\$ 115.00
8	1	Tailgate Wheatherstrip	Cut	\$ 395.00	\$ 395.00
9	1	Tail lamp L/R	Cut	\$ 800.00	\$ 800.00
10	1	Rear Bumper	Deformed	\$ 525.00	\$ 525.00
11	2	Rear Bumper Side Retainer L/R	Necessary	\$ 60.00	\$ 60.00
12	2	Rear Bumper Corner Cover L/R	Cut	\$ 160.00	\$ 160.00
13	4	Rear Bumper Lower Bracket	Necessary	\$ 120.00	\$ 120.00
14	1	End Panel Outer	Dent	\$ 422.00	\$ 422.00
15	1	End Panel Inner	Dent	\$ 950.00	\$ 950.00 <i>27 R</i>
16	1	End Panel Top Trim	Dent	\$ 188.00	\$ 188.00
17	1	Rear Fender LH	Repair	\$ 1,400.00	\$
18	1	Spare Tyre Bracket	Dent	\$ 266.00	\$ 266.00 <i>Xr</i>
Parts Cost:				\$ 7,855.70	\$ 6,250.70
Discount 25%:				\$ 1,963.93	\$ 1,562.68
Total Parts Cost:				\$ 5,891.77	\$ 4,688.02

Annex B.2

SPECIAL NETT ITEMS

No.	Qty	Description	Condition	Repairer's Estimation	Revised Amount
1	1	Windscreen Sealant	Necessary	\$ 100.00	\$ 80.00 <i>50 R</i>
2	1	Tailgate Inner Trim Clips	Necessary	\$ 50.00	\$ 30.00
3	1	Rear Bumper Clips	Necessary	\$ 50.00	\$ 30.00
4	2	End Panel Sealant	Necessary	\$ 200.00	\$ 160.00 <i>80</i>
5	1	70Km/h Sticker	Necessary	\$ 30.00	\$ 20.00
Total Special Nett Items Cost:				\$ 400.00	\$ 320.00

U.T APPRAISAL
UNI TEAM (SERVICES) PTE LTD

Email: Uniteam.ops@gmail.com Tel: 91903920

Our Reference: 2206/MEC/1006

Vehicle Reg No: GBL1775D

Annex B.3

RECOMMENDED LABOUR

No.	Description	Repairer's Estimation	Revised Amount
1	Wire Check	\$ 50.00	\$ 30.00 ✓
2	Remove & Refit Rear Windscreen	\$ 180.00	\$ 120.00 ✓
3	Transfer Rear Tailgate Component From Old To New	\$ 100.00	\$ 80.00 50
4	Remove & Refit Rear Garnish, Trim & Carpet To Facilitate Repairs	\$ 100.00	\$ 80.00 50
5	Tuff Coat	\$ 150.00	\$ 120.00 30
6	To provide labour charges, workmanship to dismantle above damaged parts, including cut and weld, re-alignment of body structure and damages consistent to the accident.	\$ 1,600.00	\$ 1,400.00 660 800
7	To respray paint including polishing and waxing on the replaced body parts, repaired portions where consistent to the accident.	\$ 1,400.00	\$ 1,000.00 600

Total Labour Cost: \$ 3,580.00 \$ 2,830.00

F: ~~5050~~ 4250
KDS