



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 928D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT WINDSCREEN	CRACKED / PITTED	4,989.90	4,989.90
1	SEALANT FRAME, WINDSCREEN	NECESSARY	586.30	586.30
8	SEALANT	NECESSARY	392.00	392.00
1	IU BRACKET	NECESSARY	20.00	20.00
1	FRONT ELECTRIC MIRROR LH ASSEMBLY	SERVICEABLE	1,980.90	-
1	RECORDING CAMERA LH (NPA)	SERVICEABLE	-	-
			7,969.10	5,988.20
SPECIAL NETT ITEMS				
2	SUNDRIES (SN)	NOT NECESSARY	200.00	-
			200.00	-
LABOUR				
LABOUR TO REMOVE, REINSTALL AND CHECK WIREHARNES.			650.00	320.00
LABOUR TO REMOVE AND REINSTALL FRONT WINDSCREEN.			800.00	700.00
LABOUR TO REMOVE, REPAIR AND REINSTALL FRT ELECTRIC MIRROR LH ASSEMBLY.			800.00	640.00
LABOUR TO RESPRAY FRT ELECTRIC MIRROR LH ASSY.			800.00	500.00
LABOUR TO CARRY OUT DIAGNOSTIC CHECK.			250.00	80.00
			3,300.00	2,240.00
GRAND TOTAL			11,469.10	8,228.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,600.00

Report Ref No. CS/SMO22005960/Kvy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.