

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22005970/RQY3E2**Date:** 04/01/2023**REFERENCE**

Insured/Claimant:	LEE MAY LING	Policy No:	MPC21B00019900	
Date of Loss:	17/06/2022	Nature of Claim:	OD	Claim No: DMPC2200250H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR3717J		
Make & Model:	MITSUBISHI SPACE STAR, 1.2 CVT (A)	Engine No:	3A92UGD8138
Reg. Date:	14/08/2017 (Man. Year: 2017)	Chassis No:	MMCXTA03AGH049754
Colour:	Green	Odometer:	20154 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$50,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/55 R15	Rear Tyre Size:	175/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,329.70	2,242.90	1,086.80	32.64
Miscellaneous Items	105.00	105.00	0.00	0.00
Labour	1,600.00	830.00	770.00	48.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,034.70	3,177.90	1,856.80	36.88
+ GST 7.00/7.00% (S\$)	352.43	222.45	129.98	36.88
Nett Amount (S\$)	5,387.13	3,400.35	1,986.78	36.88

INSPECTION

Date of Assignment:	22/06/2022	Present Location:	Ricardo Auto Centre Pte Ltd (HQ)
Date Inspected:	23/06/2022	Inspected At:	Ricardo Auto Centre Pte Ltd (HQ) 160 Sin Ming Drive, #02-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2023)
Parts:	144	MITSUBISHI SPACE STAR 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR3717J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT FENDER (WCP)	Bent	230.00 F	*230.00 F
2	1		*LH FRONT FENDER SHIELD (WCP)	Not Necessary	65.00 F	*- F
3	10		*LH FRONT FENDER SHIELD CLIPS (WCP)	Necessary	30.00 F	*30.00 F
4	1		*BONNET INSULATOR (WCP)	Not Necessary	90.00 F	*- F
5	10		*BONNET INSULATOR CLIPS (WCP)	Not Necessary	30.00 F	*- F
6	1		*HEAD LAMP - LH (WCP)	Cracked	1,200.00 F	*1,200.00 F
7	1		*FRONT BUMPER (WCP)	Cracked	450.00 F	*400.00 F
8	1		*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	210.00 F	*- F
9	10		*FRONT BUMPER CLIPS (WCP)	Necessary	35.00 F	*35.00 F
10	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Cracked	10.00 F	*10.00 F
11	1		*FRONT BUMPER FOG LAMP LH (FOG LAMP COVER)(WCP)	Scratched	38.00 F	*38.00 F
12	1		*FRONT BUMPER FOG LAMP GARNISH SIDE LH (WCP)	Scratched	68.00 F	*68.00 F
13	1		*HEAD LAMP SUPPORT LH (WCP)	Not Necessary	55.00 F	*- F
14	1		*FRONT SUPPORT PANEL (WCP)	Not Necessary	450.00 F	*- F
15	1		*FENDER EMBLEM (WCP)	Not Necessary	38.00 F	*- F
16	1		*FENDER CHROME GARNISH (WCP)	Necessary	28.00 F	*28.00 F

F=Franchise part.

Sub Total (\$\$)	3,027.00	2,039.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	302.70	203.90
Total Parts (\$\$)	3,329.70	2,242.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Supplementary #1				
1	1	SUPPLY WEEK END CAR PLATE (NECESSARY)	45.00	45.00
2	1	WEEK END CAR BREAK SEAL & LOCK SEAL ENABLE TO REMOVE & REPLACE FRONT BUMPER (NECESSARY)	60.00	60.00
Sub Total (\$)			105.00	105.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO FOCUS HEADLAMP	New	30.00	30.00
2	TO CUT, WELD & STRAIGHTEN FRONT PORTION OF CAR CAUSED BY ACCIDENT. ADJUST & REPLACE DAMAGE PARTS.	New	650.00	400.00
3	TO SERVICE AIRCON SYSTEM, VACUUM & TOP UP GAS.	New	120.00	0.00
4	TO SPRAY PAINT ON REPAIRED AREAS	New	800.00	400.00
Gross Labour Cost (\$)			1,600.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >