

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22005976/AVCE2**Date:** 27/09/2022**REFERENCE**

Insured/Claimant:	TIONG YONG WEI, DAVID	Policy No:	2070007814-01	
Date of Loss:	17/06/2022	Nature of Claim:	OD	Claim No: 8413076050SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGG5330U		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZD885227
Reg. Date:	21/01/2020 (Man. Year: 2019)	Chassis No:	WAUZZZF32L1024380
Colour:	Red	Odometer:	50438 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,364.00	792.80	10,571.20	93.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,972.00	2,272.00	3,700.00	61.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,336.00	3,064.80	14,271.20	82.32
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	16,936.00	2,664.80	14,271.20	84.27
+ GST 7.00/7.00% (S\$)	1,185.52	186.54	998.98	84.27
Nett Amount (S\$)	18,121.52	2,851.34	15,270.18	84.27

INSPECTION

Date of Assignment:	23/06/2022	
Date Inspected:	22/06/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,073.00 FS	*- FS
2	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	66.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - RH	Not Necessary	124.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	212.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Cut	426.00 FS	*340.80 FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	171.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	43.00 FS	*- FS
8	1		*FRONT FENDER - RH	Repair	1,445.00 FS	*- FS
9	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	66.00 FS	*- FS
10	1		*FRONT FENDER BRACE - RH	Not Necessary	98.00 FS	*- FS
11	1		*FRONT FENDER BRACKET - RH	Not Necessary	39.00 FS	*- FS
12	1		*FRONT WHEEL HOUSING LINER	Not Necessary	260.00 FS	*- FS
13	1		*FRONT WHEEL HOUSING LINER COVER - RH	Not Necessary	18.00 FS	*- FS
14	2		*FRONT WHEEL COVER - LH / RH	Necessary	566.00 FS	*452.00 FS
15	1		*HEADLIGHT MOUNTING - RH	Not Necessary	132.00 FS	*- FS
16	1		*LIFT CYLINDER - RH	Not Necessary	231.00 FS	*- FS
17	1		*LIFT CYLINDER HOSE	Not Necessary	92.00 FS	*- FS
18	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS
19	1		*HEADLIGHT - RH	Not Necessary	5,952.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	11,364.00 792.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,972.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >