

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22005978/AVCE2**Date:** 02/11/2022**REFERENCE**

Insured/Claimant:	GOH SOON YONG	Policy No:	1900230537-02	
Date of Loss:	16/06/2022	Nature of Claim:	OD	Claim No: 1028348188SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ1090P	Engine No:	CZD886363
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF38L1011911
Reg. Date:	30/10/2019 (Man. Year: 2019)	Odometer:	24230 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$156,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,676.00	2,286.88	2,389.12	51.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,152.00	2,152.00	2,000.00	48.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,828.00	4,438.88	4,389.12	49.72
+ GST 7.00/7.00% (S\$)	617.96	310.72	307.24	49.72
Nett Amount (S\$)	9,445.96	4,749.60	4,696.36	49.72

INSPECTION

Date of Assignment:	23/06/2022		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	22/06/2022	Inspected At:	55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,738.00 FS	*1,390.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	220.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	510.00 FS	*408.00 FS
4	1		*REAR BUMPER REINFORCEMENT - CENTER	Not Necessary	108.00 FS	*- FS
5	1		*REAR BUMPER BRACKET	Not Necessary	53.00 FS	*- FS
6	1		*REAR LIGHT REFLECTOR - RH	Cracked	46.00 FS	*36.48 FS
7	1		*TAIL LIGHT - RH OUTER	Not Necessary	1,030.00 FS	*- FS
8	1		*TAIL LIGHT TRIM OUTER - RH	Not Necessary	34.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	71.00 FS	*- FS
10	2		*REAR WHEEL ARCH COVER - LH / RH	Necessary	566.00 FS	*452.00 FS
11	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
					Total Parts (S\$)	4,676.00 2,286.88

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
2	TO RESPRAY REAR BUMPER AND RHS REAR FENDER	New	2,000.00	1,100.00
3	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
4	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
Gross Labour Cost (\$)			4,152.00	2,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >