

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005979/UCY3E2

Date: 07/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00054612201
Claimant Vehicle No : FBR3062H **Insured Vehicle No :** SJW4568M
Date of Loss: 17/06/2022 Nature of Claim: TP Claim No: SNM22D204295/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBR3062H**
Make & Model: YAMAHA T150, 150cc Engine No: G3P3E0001349
Reg. Date: 02/04/2020 (Man. Year: 2020) Chassis No: MH3UG131000001316
Colour: Multi-colour Odometer: 23981 km
Engine Capacity: 150 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17 Rear Tyre Size: 80/90-17
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 2,434.90 | 1,813.90 | 621.00 | 25.50 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 340.00 | 310.00 | 30.00 | 8.82 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 2,774.90 | 2,123.90 | 651.00 | 23.46 |

INSPECTION

Date of Assignment: 23/06/2022
Date Inspected: 23/06/2022 Inspected At: Teo Spray Painting (HQ)
BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558
Singapore 539187
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | (Last Synchronised: 07 Jul 2022) | |
| Parts: | N/A | YAMAHA T150 150cc (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for FBR3062H) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------|----------------|------------|------------|
| 1 | 1 | | *FRONT FORK | Bent / Twisted | 350.00 FL | *350.00 FL |
| 2 | 1 | | *UNDERBRACKET | Bent | 280.00 FL | *280.00 FL |
| 3 | 1 | | *STEERING CONE | Necessary | 95.00 FL | *95.00 FL |
| 4 | 1 | | *FRONT FENDER | Cracked | 38.00 FL | *38.00 FL |
| 5 | 1 | | *FRONT DISC | Not Necessary | 95.00 FL | *- FL |
| 6 | 1 | | *FRONT RIM | Repair | 280.00 FL | *- FL |
| 7 | 1 | | *HORN COVER | Cut | 48.00 FL | *48.00 FL |
| 8 | 1 | | *LAMP BLACK COVER | Deformed | 45.00 FL | *45.00 FL |
| 9 | 1 | | *HANDLE BAR | Serviceable | 65.00 FL | *- FL |
| 10 | 1 | | *BALANCER RH | Missing | 48.00 FL | *48.00 FL |
| 11 | 1 | | *FRONT PILOT LIGHT | Not Necessary | 250.00 FL | *- FL |
| 12 | 1 | | *FRONT SIDE COVER RH | Cracked | 48.00 FL | *48.00 FL |
| 13 | 1 | | *FRONT SIGNAL LH | Scratched | 48.00 FL | *48.00 FL |
| 14 | 1 | | *FRONT FOOTREST RH | Broken | 35.00 FL | *35.00 FL |
| 15 | 1 | | *REAR BRAKE PANEL | Bent | 45.00 FL | *45.00 FL |
| 16 | 1 | | *FOOTREST BRACKET | Bent | 45.00 FL | *45.00 FL |
| 17 | 1 | | *TAIL COVER LH | Cracked | 50.00 FL | *50.00 FL |
| 18 | 1 | | *TAIL COVER RH | Cracked | 50.00 FL | *50.00 FL |
| 19 | 1 | | *PILLION BAR | Cut | 120.00 FL | *120.00 FL |
| 20 | 1 | | *EXHAUST PROTECTOR | Cut | 45.00 FL | *45.00 FL |
| 21 | 1 | | *EXHAUST COVER | Cut | 45.00 FL | *45.00 FL |
| 22 | 1 | | *REAR SIGNAL LH | Broken | 40.00 FL | *40.00 FL |
| 23 | 1 | | *TOP BOX | Cut | 250.00 FS | *250.00 FS |
| 24 | 1 | | *BOX RACK | Bent | 150.00 FS | *150.00 FS |
| 25 | 1 | | *LOWER BLACK COVER LH | Cut | 48.00 FL | *48.00 FL |
| 26 | 1 | | *LOWER BLACK COVER RH | Cut | 48.00 FL | *48.00 FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 2,661.00 | 1,971.00 |
| - List Item Discount on L Items 10.00/10.00% (\$) | 226.10 | 157.10 |
| Total Parts (\$) | 2,434.90 | 1,813.90 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|----------------|----------|---------------|---------------|
| Labour Items | | | | |
| 1 | TRANSPORT | New | 60.00 | 60.00 |
| 2 | LABOUR CHARGES | New | 280.00 | 250.00 |
| Gross Labour Cost (S\$) | | | 340.00 | 310.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >