LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005981/AVY3E2

14/07/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00099292102

Claimant Vehicle

SMC2839P

Insured

GBJ8081L

No:

Vehicle No:

Date of Loss:

18/06/2022

Nature of Claim: TP

Claim

Engine No:

Chassis No:

Odometer:

SNM22D204331/C02/LEWLC

JHMFD16306S210310

Yes

R18A11033647

134494 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMC2839P Reg No:

Make & Model: HONDA CIVIC, 1.8 (A)

Reg. Date: 20/07/2006 (Man. Year: 2006)

1799 cc

Colour: White

Engine Capacity:

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18 Front Left Side: Rear Left Side: Tourador 6 mm Tourador 6 mm Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,798.96	4,837.84	9,961.12	67.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	1,530.00	1,530.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,858.96	6,367.84	11,491.12	64.34
Approved Total (Overridden) (S\$)		5,100.00		
Nett Amount (S\$)	17,858.96	5,100.00	12,758.96	71.44

INSPECTION

Date of Assignment: 23/06/2022

KS AUTOMOBILE (HQ)

Date Inspected: 24/06/2022 Inspected At:

60 JALAN LAM HUAT, CARROS CENTRE, #05-68

Singapore 737869

Estimated Period of Repair: 6.0 days

Adjuster: **ADRIAN LING** Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Jul 2022)

Parts: HONDA CIVIC 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMC2839P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	868.30 FL	*638.00 FL
2	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	324.10 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	398.60 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER	N/S Damaged	124.40 FL	*32.00 FL
5	1		*FRONT BUMPER FOG LAMP LH	Cracked	425.20 FL	*224.00 FL
6	1		*FRONT GRILLE EMBLEM	Not Necessary	93.50 FL	*- FL
7	1		*BONNET	Buckled	1,022.40 FL	*606.00 FL
8	2		*BONNET HINGE	Not Necessary	117.80 FL	*- FL
9	1		*BONNET LOCK	Not Necessary	258.20 FL	*- FL
10	1		*FRONT FENDER LH	Distorted	612.00 FL	*537.00 FL
11	1		*FRONT FENDER INNER SHIELD	N/S Torn	238.80 FL	*165.00 FL
12	1		*FRONT SUPPORT PANEL	Not Necessary	785.20 FL	*- FL
13	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	321.20 FL	*- FL
14	1		*HEADLAMP	N/S Cut	2,048.00 FL	*912.00 FL
15	2		*HEADLAMP LOWER BRACKET	Not Necessary	248.00 FL	*- FL
16	1		*A/C CONDENSER	Not Necessary	1,542.00 FL	*- FL
17	1		*RADIATOR	Not Necessary	1,574.60 FL	*- FL
18	1		*RADIATOR RESERVE TANK	Not Necessary	147.30 FL	*-FL
19	1		*RESONATOR CHAMBER	Cut	356.40 FL	*189.00 FL
20	1		*FRONT KNUCKLE ARM LH	Damaged	490.50 FL	*490.50 FL
21	1		*FRONT KNUCKLE BEARING	Damaged	202.80 FL	*202.80 FL
22	1		*FRONT LOWER ARM LH	Bent	473.90 FL	*258.00 FL
23	1		*FRONT STABILIZER LINK LH	Not Necessary	187.60 FL	*- FL
24	1		*FRONT ABSORBER ASSY LH	Bent	585.70 FL	*343.00 FL
25	1		*STEERING TIE ROD	Not Necessary	127.20 FL	*- FL
26	1		*SET FRONT BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
27	1		*FRONT BUMPER LOWER SPOILER	Deformed	1,200.00 FS	*650.00 FS
28	1		*FRONT GRILLE	Not Necessary	800.00 FS	*-FS
29	1		*FRONT GRILLE EMBLEM PUSH NUT	Not Necessary	10.00 FS	*-FS
30	1		*SET BONNET INSULATOR CLIP	Not Necessary	70.00 FS	*-FS
31	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	95.00 FS	*30.00 FS
32	1		*SPORT RIM	Cut	1,500.00 FS	*450.00 FS
33	1		*SET WHEEL CAP	Not Necessary	150.00 FS	*-FS
34	2		*ENGINE COOLANT	Not Necessary	50.00 FS	*-FS
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.			

Sub Total (S\$) - List Item Discount on L Items 20.00/20.00% (S\$)	17,513.70 2,714.74	5,757.30 919.46
Total Parts (S\$)	14,798.96	4,837.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	CUT OFF AND REPLACE FRONT SUPPORT PANEL. RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS	New	1,000.00	600.00
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA	New	1,000.00	600.00
3	ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	New	80.00	30.00
4	REMOVE AND INSTALL FRONT LHS UNDER-CARRIAGE COMPONENT	New	300.00	220.00
5	WHEEL ALIGNMENT	New	150.00	80.00
6	REMOVE AND INSTALL RADIATOR ASSY. PERFORMED RADIATOR PRESSURE TEST	New	150.00	0.00
7	PASSENGER AIR-BAG, WIRING HARNESS, SEAT BELTS AND SRS CONTROL UNIT. RESET SRS SYSTEM WITH ON-BOARD DIAGNOSTIC	New	200.00	0.00
8	DISMENTLE AND REPLACE A/C CONDENSER ASSY. REFILL, RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST	New	180.00	0.00
	Gross Labour	Cost (S\$)	3,060.00	1,530.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >