

ASS. REC. BY: Tauhin

REF:

CS / ASUM 2705983 / TVYS

2029 Jan.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SHC 8042R

Policy No. _____

Claims No. S2M04292

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Bal. or Market Value: \$81K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJN 2179M Yr Regn: 2009, Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Crossroad 1.8 cc 1799

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 232915 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RT11008304

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Mod: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 24/5/2022 D.O.I. 24/8/22 02pm

Survey held at Xin Yun

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|--|
| 9/6/23 | Lump sum \$1250 confirmed by email (Red 4330, 77%) |
| | |
| | |
| | |
| | |
| | |

Date/Time, File Pass to? : Prel. Report : Final Report

Days Of Repair: 3
Resurvey No. of Trip: _____

1) Date/Time, File Return to?
2) 9/6/23-typist

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

| | |
|-----------------|--|
| Survey Fee: | |
| Transportation: | |
| \$ + RS. SI | |
| Photos | |
| Others | |
| TOTAL | |

Rep. Format: TP
Lump Sum / FB: (\$1250)



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SJN2179M HONDA CROSSROAD

| No | Qty | Parts Description | Estimated |
|----|-----|--------------------------|--|
| 1 | 1 | Front side mirror motor | \$ 1,500.00 <i>b/w ✓ 589.30</i> 689.30 |
| 2 | 1 | Front side mirrr cover | \$ 280.00 <i>open ✓ 140</i> 160 |
| 3 | 1 | Front side mirror glass | \$ 250.00 <i>x w</i> |
| 4 | 1 | Side triangle cover trim | \$ 300.00 <i>cut ✓ 150</i> 170 |
| | | Sub-total | \$ 2,530.00 |

879.30
20% - 703.44



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SJN2179M HONDA CROSSROAD

| No | Qty | Parts Description | Estimated |
|---------------------------|-----|--|--------------------|
| <u>Special Nett Items</u> | | | |
| 1 | 10 | Front door inner board clips | \$ 100.00 <i>x</i> |
| 2 | 8 | Front side fender clips | \$ 80.00 <i>x</i> |
| 3 | 8 | Front right fender inner cowling clips | \$ 80.00 <i>x</i> |
| | | Special Nett Items | \$ 260.00 |



Xin Yun Auto Private Limited
 幸运汽车服务有限公司
 Tel: 6634 0858 Email: xinyunauto1@gmail.com
 Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SJN2179 HONDA CROSSROAD

| No | Description | Labour Charges |
|----------------------------|---|----------------------------|
| 1 | Labour for panel beating, cut, weld, straighten front affected area | \$ 1,000.00 <u>200</u> 350 |
| 2 | To putty and spray painting frontdoor, touch up fender even color | \$ 700.00 <u>300</u> 350 |
| 3 | To apply anti rust proofing to front affected area. | \$ 120.00 30 |
| 4 | To remove and install front undercarriage parts. | \$ 120.00 X |
| 5 | To balance front wheel. | \$ 60.00 X |
| 6 | To conduct wheel alignment. | \$ 120.00 X |
| 7 | To remove and install side mirror, side mirror cover and side mirror motor etc, and check performance | \$ 350.00 X |
| 8 | To remove and install door inner cover trim and window trim to assist this replacement side mirror | \$ 200.00 X |
| 9 | Water test after repair | \$ 120.00 X |
| Total labour : | | \$ 2,790.00 |
| Total labour : | | 2,790.00 |
| Total repair cost : | | 2,790.00 |

630

LKK Auto Consultants hereby notify the Repairer of the following

- To resurvey before/after spray painting
- To display damaged parts) for resurvey
- Parts prices are subject to negotiation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

703.44
630
 1333.44
 21591050
 03 days