

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd  
64 Cecil Street, #04-00 IOB Building  
Singapore 049711

**Our File No:** CS/III22005988/KQY3E2

**Date:** 19/09/2022

### REFERENCE

Insured/Claimant: COMFORTDELGRO MEDCARE PTE LTD  
Date of Loss: 17/06/2022

Policy No: D22MFL0001917  
Nature of Claim: OD

Claim No: MFL2022D0003181

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC9606M**  
Make & Model: TOYOTA HIACE, 3.0 D HIGH ROOF COMMUTER TURBO (A) Engine No: 1KDB069053  
Reg. Date: 26/03/2021 (Man. Year: 2020) Chassis No: JTFST22P300040327  
Colour: White Odometer: 27980 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: S\$89,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8  
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm  
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,518.00	1,193.50	324.50	21.38
Miscellaneous Items	386.00	306.00	80.00	20.73
Labour	2,030.00	1,720.00	310.00	15.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,934.00</b>	<b>3,219.50</b>	<b>714.50</b>	<b>18.16</b>
<b>- Excess (S\$)</b>	<b>0.00</b>	<b>2,000.00</b>	<b>-2,000.00</b>	
<b>(S\$)</b>	<b>3,934.00</b>	<b>1,219.50</b>	<b>2,714.50</b>	<b>69.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>275.38</b>	<b>85.37</b>	<b>190.01</b>	<b>69.00</b>
<b>Nett Amount (S\$)</b>	<b>4,209.38</b>	<b>1,304.87</b>	<b>2,904.51</b>	<b>69.00</b>

### INSPECTION

Date of Assignment: 23/06/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)  
Date Inspected: 23/06/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun Industrial Park A  
Singapore 768761  
Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

**Part Source:** (Last Synchronised: 19 Sep 2022)

**Parts:** N/A TOYOTA HIACE 3.0 D HIGH ROOF COMMUTER TURBO (A) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for PC9606M)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*1 PC REAR BUMPER</b> (WCP)	Bent	155.00 F	*155.00 F
2	1		<b>*6 PCS REAR BUMPER CLIPS @2/PC</b> (WCP)	Necessary	12.00 F	*12.00 F
3	1		<b>*1 PC TAILGATE</b> (WCP)	Bent	850.00 F	*850.00 F
4	1		<b>*1 PC TAILGATE LOGO</b> (WCP)	Necessary	38.00 F	*38.00 F
5	1		<b>*1 PC TAILGATE INNER LOCK</b> (WCP)	Repair	125.00 F	*- F
6	1		<b>*1 PC TAILGATE STICKER (HIACE)</b> (WCP)	Necessary	30.00 F	*30.00 F
7	1		<b>*1 PC REAR PANEL OUTER</b> (WCP)	Repair	170.00 F	*- F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>1,380.00</b>	<b>1,085.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	138.00	108.50
<b>Total Parts (\$\$)</b>	<b>1,518.00</b>	<b>1,193.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	1 PC HANDICAPPED STICKER (NECESSARY)	30.00	30.00
2	1	1 PC REAR WINDSCREEN GLASS GUM (NECESSARY)	40.00	40.00
3	1	1 PC STICKER - 60KM/H (NECESSARY)	10.00	10.00
4	1	1 PC STICKER - ME 106 (NECESSARY)	15.00	15.00
5	1	OD/TP Case (Insurer)	11.00	11.00
<b>Supplementary #1</b>				
6	1	1SET REVERSE SENSOR (SHORTED)	280.00	200.00
			<b>Sub Total (\$\$)</b>	<b>386.00</b>
				<b>306.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
2	REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, REAR WIPER ASSY, LOCK ASSY, TO CUT, WELD & RENEW REAR PANEL OUTER AND REALIGN THE SAME	New	800.00	650.00
3	PUTTY & RESPRAY ON REAR END PANEL, REAR BUMPER, TAILGATE	New	800.00	660.00
4	REMOVE & REFIX REVERSE CAMERA, CCTV RECORDER, REVERSE SENSOR AND RESET SYSTEM	New	80.00	60.00
<b>Supplementary #1</b>				
<b>Labour Items</b>				
5	REWRITE ADVERTISEMENT	New	250.00	250.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,030.00</b>
				<b>1,720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >